

AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aacls.com

Company Registration No.: 201325787M

GST Reg No.: 201325787M



bizSAFE₄

TO:

China Taiping Insurance (S) Pte Ltd - Claims Dept
3 Anson Rd,
#16-00 Springleaf Tower
Singapore 079909

Quotation

DATE: 01-Apr-21

TERMS: 30 Days

PAGE NO.: Page 1 of 1

S.N	DESCRIPTION	UOM	QTY	UNIT PRICE	AMOUNT (\$)
	Own Damage Repair : YP1719Z DOA: 29/03/21				
1	CABIN ASSY / <i>DD ?</i>		1	\$30,000.00	\$ 30,000.00 ✓
2	CABIN SUPPORT ASSY		1	\$3,000.00	\$ 3,000.00 ✓
3	DASHBOARD ASSY		1	\$2,000.00	\$ 2,000.00 ✓
4	BOX PANEL LH / <i>BR BR</i>		5	\$300.00	\$ 1,500.00 ✓
5	LABOUR TO DISMANTLE/REPLACE ABOVE-MENTIONED PARTS, PANEL BEATING & SPRAYPAINTING				<i>3000</i> \$4,000.00 ✓
REMARKS : ABOVE-MENTIONED IS LUMPSUM REPAIR ESTIMATE					
<i>Steve CLKK) DD-NH AL</i> <i>8322 8813 EXcess - 1800</i> <i>LIS</i> <i>My AL</i> <i>15 days</i> <i>9/4/21, 1.30pm</i> <i>36500</i> <i>LIS - 29,200</i> <i>D</i>					
E. & O. E.				SUB-TOTAL	\$40,500.00
SGD: FORTY-THREE THOUSAND THREE HUNDRED THIRTY-FIVE AND CENTS ZERO ONLY.				7% GST	\$2,835.00
				TOTAL	\$43,335.00

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd.".

Accepted and Confirmed by

AAK LOGISTICS SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

Company Chop & Signature

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Peijuan

Authorised Signature