



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004524/Utf3n2	
			Date: 16/04/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKL 9244K	Veh. Inspected	SMT 6341S
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101095/MYE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	09/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W 316I (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WBA3A16020NS38536	Colour	GREY
	Odometer	80544 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	GOODYEAR	6 mm
	L/H Front Tyre	225/45 R18	GOODYEAR	6 mm
	R/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
	L/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/04/2021	Inspection Date	09/04/2021
	Survey held at	NINETEEN AUTOWERKS PTE. LTD. 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	