

◀	<	1	of 2 ?	>	▶	↺	↻	100%	▼	📄	▼	🖨	Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	-------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
SOMPO INSURANCE SINGAPORE PL		Ref:	CS/SMO21004524/Utf3			
50 RAFFLES PLACE #03-03		Date:	09/04/2021			
SINGAPORE LAND TOWERS SINGAPORE 048623		Code:	SMO			
1. Policy Particulars :- THIRD PARTY CLAIM						
Insured Veh.	SKL 9244K	Veh. Inspected	SMT 6341S			
Policy No.		Coverage (\$)	0.00			
Claim No.	CMTD2101095/MYE	Excess (\$)	0.00			
Assign From	GRACE TEO	Assign Date	09/04/2021			
2. Vehicle Particulars & Condition						
Make & Model		c.c	0			
Engine No.	HIDDEN	Year of Reg.				
Chassis No.		Colour				
Odometer	-	Steering				
Brakes		Modification				
General						
3. Conditions of Tyres						
	Size	Make	Balance			
R/H Front Tyre			mm			
L/H Front Tyre			mm			
R/H Rear Tyre			mm			
L/H Rear Tyre			mm			
4. Description of Damages						
5. General Information						
Accident Date	07/04/2021	Inspection Date	09/04/2021			
Survey held at	NINETEEN AUTOWERKS PTE. LTD. 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807					
5a. Remarks						
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						