



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Notated  
Benny B repair  
9 day!

TO :  
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SKN8847S

ESTIMATE REPORT 1st QUOTATION  
OWNER'S PARTICULAR

JOB NO. : \_\_\_\_\_

11/11/21 @ 5200h

NAME : YEONG THIM  
ADDRESS :

CONTACT :

LICENSE NO. SMU4713K TRANS. :  
MAKE / MODEL : HONDA VEZEL  
OWNER'S INSURER : AXA INSURANCE (AGAINST AIG)  
JOB-CODE : TP S/A : MICHELLE

CHASSIS NO :  
ENGINE NO :

ACCIDENT DATE : 7-Apr-21

CLAIM DETAIL

MATERIALS	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR	REV. PRICE
1 FRONT BUMPER <i>801-70</i>	<i>Ry</i> 1.00	927.50	20.00	742.00	Y	<input checked="" type="checkbox"/>
2 FRONT BUMPER LOWER GARNISH <i>nd Diff</i>	<i>Ry</i> 1.00	300.70	20.00	240.56	Y	<input checked="" type="checkbox"/>
3 FRONT BUMPER RETAINER LH	<i>Ry</i> 1.00	38.00	20.00	30.40	Y	<input checked="" type="checkbox"/>
4 FRONT BUMPER RETAINER RH	<i>Ry</i> 1.00	38.00	20.00	30.40	Y	<input checked="" type="checkbox"/>
5 FRONT BUMPER LOWER GRILLE <i>167</i>	<i>Ry</i> 1.00	180.00	20.00	144.00	Y	<input checked="" type="checkbox"/>
6 FRONT BUMPER TOWING COVER	<i>Ry</i> 1.00	38.00	20.00	30.40	Y	<input checked="" type="checkbox"/>
7 FRONT BUMPER REINFORCEMENT	<i>Ry</i> 1.00	321.00	20.00	256.80	Y	<input checked="" type="checkbox"/>
8 FRONT HEADLAMP RH	<i>Ry</i> 1.00	1716.70	20.00	1373.36	Y	<input checked="" type="checkbox"/>
9 FRONT HEADLAMP LH	<i>Ry</i> 1.00	1716.70	20.00	1373.36	Y	<input checked="" type="checkbox"/>
10 FRONT HEADLAMP LOWER BRACKET LH <i>35</i>	<i>Ry</i> 1.00	70.00	20.00	56.00	Y	<input checked="" type="checkbox"/>
11 FRONT HEADLAMP LOWER BRACKET RH <i>35</i>	<i>Ry</i> 1.00	70.00	20.00	56.00	Y	<input checked="" type="checkbox"/>
12 FRONT HEADLAMP TOP RH	<i>Ry</i> 1.00	168.00	20.00	134.40	Y	<input checked="" type="checkbox"/>
13 FRONT HEADLAMP TOP LH	<i>Ry</i> 1.00	168.00	20.00	134.40	Y	<input checked="" type="checkbox"/>
14 FRONT CHROME	<i>Ry</i> 1.00	108.00	20.00	86.40	Y	<input checked="" type="checkbox"/>
15 FRONT GRILLE <i>1090 55.00</i>	<i>Ry</i> 1.00	128.00	20.00	102.40	Y	<input checked="" type="checkbox"/>
16 FRONT GRILLE TOP COVER <i>105</i>	<i>Ry</i> 1.00	250.00	20.00	200.00	Y	<input checked="" type="checkbox"/>
17 FRONT RADIATOR GRILLE <i>LOGO</i>	<i>Ry</i> 1.00	285.00	20.00	228.00	Y	<input checked="" type="checkbox"/>
18 FRONT SIDE EMBLEM 'HYBRID' RH	<i>Ry</i> 1.00	68.00	20.00	54.40	Y	<input checked="" type="checkbox"/>
19 FRONT SIDE EMBLEM 'HYBRID' LH	<i>Ry</i> 1.00	68.00	20.00	54.40	Y	<input checked="" type="checkbox"/>
20 FRONT FOG LAMP RH	<i>Ry</i> 1.00	327.70	20.00	262.16	Y	<input checked="" type="checkbox"/>
21 FRONT FOG LAMP LH	<i>Ry</i> 1.00	327.70	20.00	262.16	Y	<input checked="" type="checkbox"/>
22 FRONT FOG LAMP COVER RH	<i>Ry</i> 1.00	85.00	20.00	68.00	Y	<input checked="" type="checkbox"/>
23 FRONT FOG LAMP COVER LH	<i>Ry</i> 1.00	85.00	20.00	68.00	Y	<input checked="" type="checkbox"/>
24 FRONT FENDER RH	<i>Ry</i> 1.00	580.00	20.00	464.00	Y	<input checked="" type="checkbox"/>

25	FRONT FENDER LH	<i>M</i>	1.00	580.00	20.00	464.00	Y	<u>X</u>
26	FRONT FENDER WHEEL ARCH PROTECTOR RH	<i>M/CM</i>	1.00	156.20	20.00	124.96	Y	<u>X</u>
27	FRONT FENDER WHEEL ARCH PROTECTOR LH	<i>7</i>	1.00	156.20	20.00	124.96	Y	<u>X</u>
28	FRONT FENDER INNER SHIELD RH	<i>S<sub>2</sub></i>	1.00	130.10	20.00	104.08	Y	<u>X</u>
29	FRONT FENDER INNER SHIELD LH	<i>S<sub>2</sub></i>	1.00	130.10	20.00	104.08	Y	<u>X</u>
31	HORN HIGH	<i>S<sub>2</sub></i>	1.00	40.10	20.00	32.08	Y	<u>X</u>
32	HORN LOWER	<i>S<sub>2</sub></i>	1.00	40.10	20.00	32.08	Y	<u>X</u>
33	RADAR SENSOR ASSY	<i>shop od</i>	1.00	880.00	20.00	704.00	Y	<u>X</u>
TOTAL (PARTS):				9087.50		7270.00		

PECIAL NETT ITEM

1	FRONT GRILLE CLIPS		1.00	<i>rec</i> 50.00	0.00	50.00	Y	<u>✓</u>
2	FRONT FENDER INNER SHIELD CLIPS LH & RH		1.00	<i>rec</i> 100.00	0.00	50.00	Y	<u>X</u>
3	FRONT BUMPER CLIPS		1.00	<i>rec</i> 50.00	0.00	50.00	Y	<u>✓</u>
4	FRONT BUMPER LOWER SPOILER	<i>Pr?</i>	1.00	1600.00	0.00	1600.00	Y	<u>X</u> <i>550.00</i>
5	FRONT BUMPER LOWER SPOILER SEALANT		1.00	80.00	0.00	80.00	Y	<u>X</u>
6	FRONT FENDER WHEEL ARCH PROTECTOR CLIPS	<i>~</i>	1.00	100.00	0.00	50.00	Y	<u>X</u>
7	FRONT NUMBER PLATE (LASER 3D)	<i>(B.11) cm</i>	1.00	180.00	0.00	180.00	Y	<u>60.00</u>
8	FRONT PORTION BLACK STICKER SET		1.00	800.00	0.00	800.00	Y	<u>7.00</u>
TOTAL (PARTS):				2960.00		2860.00		

ABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS		1.00	1400.00	0.00	1400.00	Y	<u>500</u>
2	SPRAY PAINTING ON ACCIDENT AREAS		1.00	1400.00	0.00	1400.00	Y	<u>600</u>
3	CHECK & REPAIR WIRING SYSTEM		1.00	120.00	0.00	120.00	Y	<u>200</u>
4	RESPRAY TUFF KOTE ON AFFECTED AREAS	<i>na</i>	1.00	100.00	0.00	100.00	Y	<u>X</u>
5	PROGRAMME RADAR COLLISION CODING		1.00	680.00	0.00	680.00	Y	<u>100</u>
TOTAL (LABOUR):				3700.00		3700.00		
TOTAL PARTS & LABOUR				15747.50		13830.00		



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO : \_\_\_\_\_ T/P VEH. NO. : SKN8847S  
ATTN : MOTOR CLAIM DEPT. -----

ESTIMATE REPORT 1st QUOTATION

JOB NO : \_\_\_\_\_

OWNER'S PARTICULAR

CONTACT : \_\_\_\_\_

NAME : YEONG THIM

ADDRESS : \_\_\_\_\_

LICENSE NO. SMU4713K TRANS. :

CHASSIS NO : \_\_\_\_\_

MAKE / MODEL : HONDA VEZEL

ENGINE NO : \_\_\_\_\_

OWNER'S INSURER : AXA INSURANCE (AGAINST AIG)

ACCIDENT DATE : 7-Apr-21

DOB-CODE : TP S/A : MICHELLE

SUPPLEMENTARY ITEMS

<u>MATERIALS</u>	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR . REV. PRICE DISP
1 RADIATOR SIDE GARNISH LH	CM 1.00	68.30	20.00	54.64	Y <u>    </u>
2 ENGINE LOWER COVER LH	CM 1.00	168.00	20.00	134.40	Y <u>    </u>

EXCESS : : \$\$ \_\_\_\_\_

NO. OF DAY : \_\_\_\_\_

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$\$ \_\_\_\_\_

DATE OF SURVEY : \_\_\_/\_\_\_/\_\_\_

SURVEY BY : \_\_\_\_\_

CONTACT NO : \_\_\_\_\_

FAX NO : \_\_\_\_\_

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.