



INVOICE

Invoice Number: 210255

Date: 29/01/2021

Due Date: 29/01/2021

Payment Term: COD

160 Sin Ming Drive #03-09

Sin Ming AutoCity 575722

Licence: 202026541W

Tel: +65 64532605

Fax: +65 64533790

Email: keeyongauto@gmail.com

Website: <https://www.keeyongauto.com.sg>

BILL TO:

**NTUC INCOME INSURANCE CO-
OPERATIVE LTD**

75 Bras Basah Road # 05 - 01 NTUC

TRADE UNION HOUSE

Singapore 189557

FOR:

Vehicle Owner: CHRIS TAN

Account/Policy No.: 5107295344-01

Odometer: 216,909 Kms

Model: Jaguar XF 2.2 I4TD

Reg No: SKK1080Z

Chassis: SAJAC0567DDS81495

Year: 2013

| Description | Qty. | Unit Price | Amount |
|---|------|---------------|--------------|
| AD HOC SERVICE REPAIR AND REPLACE THE RHF FENDER, ROAD WHEEL, UNDERCARRIAGES , WING MIRROR , DOOR , DOOR PILLARS, PANEL MOULDING, ETC TO PRE-ACCIDENT CONDITION | 1.0 | S\$26,000.000 | S\$26,000.00 |
| - RHF FENDER, RHF FINDER FINISHER AND RHF FENDER INNER SHIELD | | | |
| - RHF RIM, | | | |
| - RHF WHEEL BEARING HUB | | | |
| - RHF KNUCKLE ARM | | | |
| - RHF SPRING STRUT, | | | |
| - RHF UPPER ARM , RHF LOWER ARM AND RHF LOWER ARM (RR) | | | |
| - RHF STABILIZER LINKAGE | | | |
| - RH WING MIRROR COVER, RH WING MIRROR TURN SIGNAL AND RH WING MIRROR ASSY | | | |
| - RHF DOOR, DOOR FRAME FINISHER, DOOR OUTER HANDLE , HANDLE PLATE , GLASS RUN SEAL , HINGE , CHECKER AND LOCK. | | | |
| - RHF DOOR STRIKER, WEATHER-SEAL , DOOR GLASS REGULATOR ASSY, DOOR TRIM BOARD | | | |
| - RHR DOOR, DOOR FRAME FINISHER, OUTER HANDLE, HANDLE PLATE, GLASS RUN SEAL, DOOR HINGE, CHECKER AND LOCK | | | |
| - RHR STRIKER, DOOR WEATHER-SEAL, LOWER WEATHER-SEAL, GLASS REGULATOR ASSY, TRIM BOARD | | | |
| - RHR RIM , WHEEL BEARING HUB, KNUCKLE ARM, SPRING STRUT, UPPER ARM, LOWER ARM | | | |
| - RH DRIVESHAFT , SILL PANEL MOULDING, SILL PANEL RETAINER , SILL PANEL INSERT | | | |
| - RHR STABILIZER LINKAGE | | | |
| - REAR BUMPER, BUMPER BRACKET RH | | | |
| - RHF DOOR PILLAR | | | |
| - RH DOOR CENTRE PILLAR, | | | |
| - RH SILL PANEL | | | |
| - RHR FENDER | | | |

Subtotal S\$26,000.00

GST S\$0.00

Total S\$26,000.00

Paid S\$0.00

Balance Due S\$26,000.00

Enquire Vehicle's Insurance Particulars (As At 22 Dec 2020 / 00:21:00)

Vehicle No.:

SHD4271S

Make Description/Model:

**HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG
4DR**

Insurance Company Name:

INDIA INT'L INS PTE LTD

Business Transaction Reference No.:

20201223200322551698

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

SMKYA-10599 - LTA

Printed on 23 Dec 2020 20:03:32

Copyright © Land Transport Authority of Singapore 2020



Thank you

Yap Bee Yang has successfully logged out.

Your last login date and time was 23 Dec 2020, 20:02:40.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

| S/No. | Asset Type | Asset ID | Asset Owner ID | Transaction Type | Transaction Amount(S\$) | Log Date/Time |
|-------|------------|-----------|----------------|---|-------------------------|------------------------|
| 1 | Vehicle | SHD4271S- | | 18.19 Enquire Veh Owner Info (Others) by Law Firm | 7.49 | 23 Dec 2020 / 20:03:22 |



RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Date of Request: 28/12/2020

Your Ref No: LCH.lg/SMKYA-10599.20

Dear Sir/Madam,

Date of Accident: 22/12/2020 00:00 (SGT)

Vehicle No: SKK1080Z

Place of Accident: Upper Boon Keng Rd, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

| DOCUMENTS | ACCIDENT LOCATION | PER DOC (S\$) | QTY | AMOUNT (S\$) |
|----------------------------------|-------------------------------|---------------|-----|--------------|
| SHD4271S | Upper Boon Keng Rd, Singapore | (29.00) | 1 | (27.10) |
| GST Amount | | | | (1.90) |
| Total Amount Due (GST Inclusive) | | | | (29.00) |

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

Invoice

SKK1080Z
TAN NIAP CHIANG

Invoice No : WPLIN0004836
Invoice Date : 16/1/2021
Due Date : 16/1/2021
VHA No : 4722
Referral ID : K043


| Description : | Amount |
|-------------------------------------|-------------|
| Rental for 24 Day/s @ \$140 per Day | \$ 3,360.00 |

Vehicle No : SMH4939U

Vehicle Description : Honda Shuttle Hybrid 1.5 A

Rental Period : 22/12/2020 to 15/01/2021

Total Amount Payable : \$ 3,360.00



WIN WIN RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807

VHA No: 4722

Invoice No: 1011111111

Hirer's Vehicle No: 1011111111

UEN: 201505115E

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS

Name: (as in I/C) 1011111111

NRIC / FIN No: 1011111111

Address (Res): 1011111111

Name & Address of Employer: 1011111111

Occupation: 1011111111 Driving Exp: 1011111111

Singapore Driving Licence No: 1011111111

Issue Date: 1011111111 Date of Birth: 1011111111

Tel: (O) 1011111111 (R) 1011111111 HP: 1011111111

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) 1011111111

NRIC / FIN No: 1011111111

Address (Res): 1011111111

Occupation: 1011111111 Driving Exp: 1011111111

Singapore Driving Licence No: 1011111111

Issue Date: 1011111111 Date of Birth: 1011111111

Tel: (O) 1011111111 (R) 1011111111 H/P: 1011111111

VEHICLE CHECK LIST

INDICATE: D - DENTS A - ACCIDENTS S - SCRATCHES

RIGHT FRONT TOP LEFT

REAR

MISSING / FAULTY ACCESSORIES / PARTS

REMARKS: 1011111111

Vehicle No: 1011111111 Replace Veh No: 1011111111

Mileage Out: 65087 Mileage Out: 1011111111

Make & Model: HONDA SHUTTLE HYBRID 1.5A Auto / Manual

Out : Date 22/12/2022 Time: 10:00AM

HIRE / PERIOD EXPIRY 12/11/2023 Time: 2:00PM

NON-WAIVER EXCESS=\$ 2000% (SECTION I) 2000% (SECTION II)

CHARGES

Daily 24 @\$ 140 per day \$3360 -

Weekly @\$ per week

Monthly @\$ per month

Hours @\$ per hour

Extension @\$

Delivery/Collection Service

SUB-TOTAL \$

PETROL LEVEL

Out E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F

In E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F

Fuel

Traffic / Parking Fines

TOTAL CHARGES \$

Hirer's Signature 1011111111

Additional Driver's Signature

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

*IMPORTANT

1. VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.
2. ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
3. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
4. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY. INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
5. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES. A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
6. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN " SIGNATURE OF HIRER / DRIVER " FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

| DATE IN | TIME IN | MILEAGE | CHECKED BY | REMARKS | SIGNATURE OF HIRER/DRIVER |
|------------|---------|---------|------------|---------|---------------------------|
| 22/12/2022 | 10:00 | 65087 | | | 1011111111 |



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Invoice

Customer: Tan Niap Chiang
C/o: 160 Sin Ming Drive #03-09
Sin Ming AutoCity (S) 575722

Date: 25.01.2021

Invoice No: NS-2020-281

| Description | | Amount |
|--|---------------|-----------------|
| Vehicle No: | SKK1080Z | |
| Make & Model: | Jaguar XF (A) | |
| Our reference: | AAS/2020/281 | |
| Services rendered for appraiser / inspection report | | |
| Survey Fee | | |
| Photographs | | |
| Transport Fees | | |
| Re-inspection Fees | | |
| SGD Dollar : One thousand three hundred and sixty eight dollar only | Total: | SGD \$ 1,368.00 |

Notes:

All cheques payment should be crossed and made payment to "Absolute Appraisal Services Pte Ltd"

Please indicate our "Invoice No." on the reverse side of the cheque.

Please do not hesitate to contact us should you have any enquires.



Absolute Appraisal Services Pte Ltd



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Tan Niap Chiang
C/o: 160 Sin Ming Drive #03-09
Sin Ming AutoCity (S) 575722

Date of report: 25.01.2021
Date of request: 24.12.2020
Date of inspection: 24.12.2020
Date of accident: 22.12.2020
Claim type: Third Party Claim

Report No: AAS/2020/281

Particulars of affected vehicle:

Registration no: SKK1080Z
Make/Model: Jaguar XF (A)
Year of registration: 2013
Colour: Metallic Red

Odometer: 216909 km
Engine Capacity: 2179 cc
Engine no: 4024205224DT
Chassis no: SAJAC0567DDS81495

Condition of tires:

Front Left: 6mm
Make: Kapsen
Rear Left: 6mm
Make: Kapsen

Front Right: 6mm
Make: Kapsen
Rear Right: 6mm
Make: Kapsen

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

| | |
|------------------------------|------------|
| General Bodywork | : Good |
| Paintwork | : Good |
| Handbrake | : In order |
| Footbrake | : In order |
| Steering | : In order |
| Apparent engine modification | : Nil |

The Assignment

The inspection was conducted at M/s. Kee Yong Automobile Service
160 Sin Ming Drive #03-09
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

| | |
|----------------------|-------------------------|
| Repairer's estimate: | \$ 38,842.40 |
| Revised estimate: | \$ 32,519.60 |
| Recommended reserve: | \$ 26,000.00 (Lump sum) |

Estimated normal duration of repairs : 13 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SKK1080Z

Report No: AAS/2020/281

W/O PREJUDICE

Point of impact

At the RHS portion.

General description of damages

The RHF fender, RHF road wheel, RHF undercarriages, RH wing mirror, RHF door, RHF door pillar, RHR door, RH door centre pillar, RH sill panel moulding, RH sill panel, RHR fender, RHR road wheel, RHR undercarriages, rear bumper, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Kee Yong Automobile Service as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$32,519.60

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$26,000.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 13 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 123 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SKK1080Z

Report No: AAS/2020/281

Appraisement Schedule

| S/N | Parts Description | Qty | Condition | | Repairer's Est | Revised Est |
|-----|-------------------------------|-----|-------------------------|-----------|----------------|-------------|
| 1 | RHF fender | 1 | Dented | | \$ 1,449.20 | \$ 1,449.20 |
| 2 | RHF fender finisher | 1 | Dented/Cut | | \$ 293.50 | \$ 293.50 |
| 3 | RHF fender inner shield | 1 | Refit | | \$ 278.50 | - |
| 4 | RHF rim | 1 | Dented | | \$ 1,216.00 | \$ 1,216.00 |
| 5 | RHF wheel bearing hub | 1 | Damaged | | \$ 884.50 | \$ 884.50 |
| 6 | RHF knuckle arm | 1 | Distorted | | \$ 993.20 | \$ 993.20 |
| 7 | RHF spring strut | 1 | Bent | | \$ 897.30 | \$ 897.30 |
| 8 | RHF upper arm | 1 | Bent/Torn | | \$ 661.90 | \$ 661.90 |
| 9 | RHF lower arm | 1 | Bent | | \$ 707.60 | \$ 707.60 |
| 10 | RHF lower arm (Rr) | 1 | Bent | | \$ 814.20 | \$ 814.20 |
| 11 | RHF stabilizer linkage | 1 | Refit | | \$ 67.40 | - |
| 12 | RH wing mirror cover | 1 | Grazed/Repair | | \$ 114.50 | - |
| 13 | RH wing mirror turn signal | 1 | Grazed | | \$ 122.60 | \$ 122.60 |
| 14 | RH wing mirror assy | 1 | Grazed/Repair | | \$ 1,291.80 | - |
| 15 | RHF door | 1 | Dented | | \$ 2,960.30 | \$ 2,960.30 |
| 16 | RHF door frame finisher | 1 | Necessary | | \$ 141.50 | \$ 141.50 |
| 17 | RHF door outer handle | 1 | Refit | | \$ 283.50 | - |
| 18 | RHF door handle plate | 1 | Refit | | \$ 102.70 | - |
| 19 | RHF door glass run seal | 1 | Necessary | | \$ 277.10 | \$ 277.10 |
| 20 | RHF door hinge | 2 | Distorted | \$ 131.40 | \$ 262.80 | \$ 262.80 |
| 21 | RHF door checker | 1 | Refit | | \$ 68.20 | - |
| 22 | RHF door lock | 1 | Distorted/Malfunctioned | | \$ 693.70 | \$ 693.70 |
| 23 | RHF door striker | 1 | Distorted | | \$ 75.80 | \$ 75.80 |
| 24 | RHF door weather-seal | 1 | Necessary | | \$ 190.20 | \$ 190.20 |
| 25 | RHF door lower weather-seal | 1 | Necessary | | \$ 73.20 | \$ 73.20 |
| 26 | RHF door glass regulator assy | 1 | Distorted/Malfunctioned | | \$ 526.00 | \$ 526.00 |
| 27 | RHF door trim board | 1 | Refit | | \$ 1,223.40 | - |
| 28 | RHR door | 1 | Dented | | \$ 2,866.20 | \$ 2,866.20 |
| 29 | RHR door frame finisher | 1 | Necessary | | \$ 141.50 | \$ 141.50 |
| 30 | RHR door outer handle | 1 | Refit | | \$ 283.50 | - |
| 31 | RHR door handle plate | 1 | Refit | | \$ 102.70 | - |
| 32 | RHR door glass run seal | 1 | Necessary | | \$ 277.10 | \$ 277.10 |
| 33 | RHR door hinge | 2 | Distorted | \$ 131.40 | \$ 262.80 | \$ 262.80 |
| 34 | RHR door checker | 1 | Refit | | \$ 68.20 | - |
| 35 | RHR door lock | 1 | Distorted/Malfunctioned | | \$ 578.00 | \$ 578.00 |
| 36 | RHR door striker | 1 | Distorted | | \$ 75.80 | \$ 75.80 |
| 37 | RHR door weather-seal | 1 | Necessary | | \$ 190.20 | \$ 190.20 |
| 38 | RHR door lower weather-seal | 1 | Necessary | | \$ 61.70 | \$ 61.70 |
| 39 | RHR door glass regulator assy | 1 | Distorted/Malfunctioned | | \$ 526.00 | \$ 526.00 |
| 40 | RHR door trim board | 1 | Refit | | \$ 1,043.20 | - |
| 41 | RHR rim | 1 | Dented | | \$ 1,216.00 | \$ 1,216.00 |
| 42 | RHR wheel bearing hub | 1 | Damaged | | \$ 895.00 | \$ 895.00 |
| 43 | RHR knuckle arm | 1 | Distorted | | \$ 995.10 | \$ 995.10 |



ABSOLUTE APPRAISAL SERVICES PTE LTD

LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SKK1080Z

Report No: AAS/2020/281

| | | | | | | | | | |
|----|------------------------|----|---------------|----|------|----------|-------|----------|-------|
| 44 | RHR spring strut | 1 | Bent | | \$ | 770.60 | \$ | 770.60 | |
| 45 | RHR upper arm | 1 | Bent/Torn | | \$ | 617.10 | \$ | 617.10 | |
| 46 | RHR lower arm | 1 | Bent | | \$ | 893.40 | \$ | 893.40 | |
| 47 | RH driveshaft | 1 | Bent | | \$ | 1,513.00 | \$ | 1,513.00 | |
| 48 | RHR stabilizer linkage | 1 | Bent/Torn | | \$ | 113.70 | \$ | 113.70 | |
| 49 | RH sill panel moulding | 1 | Dented | | \$ | 696.10 | \$ | 696.10 | |
| 50 | RH sill panel retainer | 10 | Necessary | \$ | 1.40 | \$ | 14.00 | \$ | 14.00 |
| 51 | RH sill panel insert | 10 | Necessary | \$ | 1.60 | \$ | 16.00 | \$ | 16.00 |
| 52 | Rear bumper | 1 | Dented/Grazed | | \$ | 2,229.70 | \$ | 2,229.70 | |
| 53 | Rear bumper bracket RH | 1 | Refit | | \$ | 65.20 | | - | |
| 54 | RHF door pillar | | Dented/Repair | | | - | | - | |
| 55 | RH door centre pillar | | Dented/Repair | | | - | | - | |
| 56 | RH sill panel | | Dented/Repair | | | - | | - | |
| 57 | RHR fender | | Dented/Repair | | | - | | - | |

List total: \$ 33,182.40 \$ 28,189.60

| | | | | | | | | |
|---|----------|---|----------|-----|----|--------|----|--------|
| 1 | RHF tyre | 1 | Refit | | \$ | 250.00 | | - |
| 2 | RHR tyre | 1 | Affected | 80% | \$ | 250.00 | \$ | 200.00 |

Special nett total: \$ 500.00 \$ 200.00

Parts Total: \$ 33,682.40 \$ 28,389.60

| S/N | Labour Description | Repairer's Est | Revised Est |
|-----|---|----------------|-------------|
| 1 | Check lightings & wirings. | \$ 50.00 | \$ 30.00 |
| 2 | Conduct wheel alignment. 2x | \$ 150.00 | \$ 120.00 |
| 3 | Renew RHF tyre & rim. | \$ 50.00 | \$ 20.00 |
| 4 | Renew RHF undercarriages. | \$ 280.00 | \$ 250.00 |
| 5 | Renew RHR tyre & rim. | \$ 50.00 | \$ 20.00 |
| 6 | Renew RHR undercarriages. | \$ 280.00 | \$ 250.00 |
| 7 | Towing charges. (King Dolly) | \$ 150.00 | \$ 150.00 |
| 8 | Remove, transfer RHF & RHR door components. | \$ 300.00 | \$ 240.00 |
| 9 | Anti rust on affected panels. | \$ 100.00 | \$ 60.00 |



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SKK1080Z

Report No: AAS/2020/281

| | | |
|--|--------------------|--------------------|
| 10 Remove & transfer reverse sensors. | \$ 100.00 | \$ 60.00 |
| 11 Remove & refit centre trimmings, step garnish, carpets to make way for repairs. | \$ 150.00 | \$ 80.00 |
| 12 Replace damaged parts, repair & align RHS affected sections. | \$ 1,500.00 | \$ 1,250.00 |
| 13 Respray replacement & affected parts. | \$ 2,000.00 | \$ 1,600.00 |
| Labour Total: | <u>\$ 5,160.00</u> | <u>\$ 4,130.00</u> |
| Grand Total: | \$ 38,842.40 | \$ 32,519.60 |

The final adjusted lump sum amount is \$26,000.00

Under normal circumstances, the repair should be completed within a reasonable period of 13 working days.

123 Photographs were taken at the time of inspection.







