

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21004537/AGS3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070033523
Claimant Vehicle No :	SKZ9743M	Insured Vehicle No :	SMS7011T
Date of Loss:	07/04/2021	Nature of Claim:	TP
		Claim No:	3235768121SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ9743M	Engine No:	G4FGFU066136
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHDH41CMGU655609
Reg. Date:	18/02/2016 (Man. Year: 2015)	Odometer:	304830 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,826.80	1,411.20	1,415.60	50.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,270.00	760.00	510.00	40.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,096.80	2,171.20	1,925.60	47.00
Approved Total (Overridden) (S\$)		1,700.00		

Nett Amount (S\$)	4,096.80	1,700.00	2,396.80	58.50
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,887.45		

INSPECTION

Date of Assignment: 09/04/2021

Date Inspected: 09/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Premium Carz Services Pte Ltd (HQ)
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Deformed	753.00 FL	*445.00 FL
2	1		*FRONT FENDER MUDFLAP RH (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*FRONT FENDER INNER SHIELD RH	Torn	92.00 FL	*92.00 FL
4	1		*FRONT DOOR RH	Dented	1,157.00 FL	*1,157.00 FL
5	1		*FRONT DOOR HINGE	Not Necessary	65.00 FL	*- FL
6	1		*FRONT DOOR STICKER RH	Not Necessary	58.00 FL	*- FL
7	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	198.00 FL	*- FL
8	1		*FRONT DOOR REGULATOR RH	Not Necessary	245.00 FL	*- FL
9	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	308.00 FL	*- FL
10	1		*FRONT DOOR SASH PILLAR BLACK STICKER RH	Necessary	45.00 FL	*45.00 FL
11	1		*ROCKER PANEL RH (NPA)	Repair	0.00 FL	*- FL
12	1		*FRONT SPORTS RIM RH	Not Necessary	450.00 FS	*- FS
13	8		*FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*20.00 FS
					Sub Total (S\$)	3,411.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	584.20
					Total Parts (S\$)	2,826.80
						1,411.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	40.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	400.00	300.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	800.00	400.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	30.00	30.00
Gross Labour Cost (S\$)			1,270.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >