

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

64 , Cecil Street # 04 - 05
 OB Building
 Singapore 049711
 Tel : 6347 - 6100
 Fax : 6224 - 4174

Quotation

DATE : 26.04.2021
 VEH NO : SLA7056X
 MODEL : Toyota Axio
 D O A : 30.03.2021
 YR REF : SKW8501S

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLA7056X (TOYOTA AXIO)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Debond</i>	1	867.40 ✓
2	Front Bumper Side Holder - LH & RH <i>new</i>	2	111.20 +
3	Front Bumper Grille <i>cracked</i>	1	398.20 ✓
4	Front Bumper Reinforcement <i>new</i>	1	347.90 +
5	Front Bumper Sponge <i>new</i>	1	110.90 +
6	Head Lamp - LH <i>new</i>	1	986.20 +
			<u>2,821.80</u>
	Less 25%		<u>(705.45)</u>
			\$ <u>2,116.35</u>

S/NET ITEMS

1	Front Bumper Clips <i>new</i>	30	1 set	30.00 ✓
Total Parts				\$ <u>2,146.35</u>

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$	400.00	150
2	To putty & spray up paint works (front)	\$	400.00	200
3	To check wiring	\$	50.00	30
Total Labour		\$	850.00	

Grand Total **\$ 2,996.35**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1459.20 (P/P)
02 Pays.