


### Yong Sing Estimate Repair

Section A - To be completed by Claims Advisor

Vehicle Registration Number : GBF 1282 R  
 Make / Model : NISSAN NV200  
 Chassis No : VSKYBAM20Z0125285  
 Year of Manufacture : \_\_\_\_\_  
 Registration Date : \_\_\_\_\_  
 Type of Repair (TP/OD/WS) : \_\_\_\_\_  
 Date/Time of Accident : \_\_\_\_\_  
 Rental Vehicle : Yes / No  
 Remark : \_\_\_\_\_

Case Ref. : \_\_\_\_\_  
No. \_\_\_\_\_

The damages on the vehicle are as indicated in the following diagram :



|                             | Yong Sing estimate breakdown cost | Adjusted by Surveyor, if applicable |
|-----------------------------|-----------------------------------|-------------------------------------|
| Total Labour Cost :         | \$ <u>2,000.00</u>                | \$ <u>-</u>                         |
| Total Spray Painting Cost : | \$ <u>1,450.00</u>                | \$ <u>-</u>                         |
| Total Spare Parts Cost :    | \$ <u>15,645.63</u>               | \$ <u>-</u>                         |
| Other Charges :             | \$ <u>750.00</u>                  | \$ <u>-</u>                         |
| <b>TOTAL</b> :              | \$ <u>19,845.63</u>               | \$ <u>-</u>                         |
| Lump Sum Repair, if any :   |                                   | \$ <u>-</u>                         |
| No. of Repair Days :        | [ 20 ] days                       | [ ] days                            |

### Surveyor Remark:

**Part 1 - Labour & Panel Beating Related Works**

| Job Scope                                                                                                          | Yong Sing Estimate | Surveyor Adjustment |
|--------------------------------------------------------------------------------------------------------------------|--------------------|---------------------|
| TO REMOVE AND REFIT DAMAGED ITEMS, TO STRAIGHT FRONT VEHICLE FRAME, CUT AND WELD SUPPORT PANEL FOR REPAIR PURPOSE. | \$2,000.00         |                     |
|                                                                                                                    |                    |                     |
| <b>Total Labour Cost</b>                                                                                           | <b>\$2,000.00</b>  | <b>\$0.00</b>       |

**Part 2 - Spray Painting Related Works**

| Job Scope                              | Yong Sing Estimate | Surveyor Adjustment |
|----------------------------------------|--------------------|---------------------|
| SPRAY PAINT FRONT BONNET.              | \$300.00           |                     |
| SPRAY PAINT LH FENDER.                 | \$200.00           |                     |
| SPRAY PAINT RH FENDER.                 | \$200.00           |                     |
| SPRAY PAINT SUPPORT PANEL              | \$200.00           |                     |
| SPRAY PAINT FRONT BUMPER.              | \$300.00           |                     |
| SPRAY PAINT LH/RH TOP WHEEL GUARD AREA | \$250.00           |                     |
|                                        |                    |                     |
|                                        |                    |                     |
|                                        |                    |                     |
| <b>Total Spray Painting Cost</b>       | <b>\$1,450.00</b>  | <b>\$0.00</b>       |

**Part 3 - Other Costs - Accident Repair Related Expenses**

| Job Scope                                     | Yong Sing Estimate | Surveyor Adjustment |
|-----------------------------------------------|--------------------|---------------------|
| CONDUCT SYSTEM WIRING CHECK.                  | \$120.00           |                     |
| TOP UP AIR CON GAS.                           | \$80.00            |                     |
| REMOVE AND REFIT FRONT WINDSCREEN FOR REPAIR. | \$120.00           |                     |
| REALIGN FRONT CHASSIS.                        | \$350.00           |                     |
| CONDUCT LEAKAGE TEST.                         | \$80.00            |                     |
|                                               |                    |                     |
|                                               |                    |                     |
|                                               |                    |                     |
|                                               |                    |                     |
| <b>Total Other Costs</b>                      | <b>\$750.00</b>    | <b>\$0.00</b>       |

**Part 4 - Spare Parts / Material Usage**

| Item                         | Part Name                             | Part No | Qty | Cost Price (\$) | Mark up (10%) | Final Price (\$) | Repair @ Replace ( / ) (Yong Sing) | Repair @ Replace ( / ) (Surveyor) |
|------------------------------|---------------------------------------|---------|-----|-----------------|---------------|------------------|------------------------------------|-----------------------------------|
| 1                            | FRONT BUMPER                          |         | 1   | \$390.00        | 10%           | \$ 429.00        | REPLACE ( / )                      |                                   |
| 2                            | BRACKET-FRONT BUMPER SIDE,RH          |         | 1   | \$123.50        | 10%           | \$ 135.85        | REPLACE ( / )                      |                                   |
| 3                            | BRACKET-FRONT BUMPER SIDE,LH          |         | 1   | \$123.50        | 10%           | \$ 135.85        | REPLACE ( / )                      |                                   |
| 4                            | FRONT BUMPER FOGLAMP COVER ,LH        |         | 1   | \$201.50        | 10%           | \$ 221.65        | REPLACE ( / )                      |                                   |
| 5                            | FRONT BUMPER FOGLAMP COVER ,RH        |         | 1   | \$201.50        | 10%           | \$ 221.65        | REPLACE ( / )                      |                                   |
| 6                            | ABSORBER-ENERGY,FRONT BUMPER          |         | 1   | \$351.00        | 10%           | \$ 386.10        | REPLACE ( / )                      |                                   |
| 7                            | REINFORCEMENT ASSY-FRONT BUMPER       |         | 1   | \$377.00        | 10%           | \$ 414.70        | REPLACE ( / )                      |                                   |
| 8                            | BUMPER-FRONT,LH                       |         | 1   | \$266.50        | 10%           | \$ 293.15        | REPLACE ( / )                      |                                   |
| 9                            | BUMPER-FRONT,RH                       |         | 1   | \$266.50        | 10%           | \$ 293.15        | REPLACE ( / )                      |                                   |
| 10                           | GRILLE ASSY-FRONT                     |         | 1   | \$351.00        | 10%           | \$ 386.10        | REPLACE ( / )                      |                                   |
| 11                           | MOULDING ASSY-RADIATOR GRILLE         |         | 1   | \$253.50        | 10%           | \$ 278.85        | REPLACE ( / )                      |                                   |
| 12                           | SUPPORT-RADIATOR CORE,UPPER           |         | 1   | \$442.00        | 10%           | \$ 486.20        | REPLACE ( / )                      |                                   |
| 13                           | SUPPORT ASSY-RADIATOR CORE,LOWER      |         | 1   | \$455.00        | 10%           | \$ 500.50        | REPLACE ( / )                      |                                   |
| 14                           | SUPPORT-RADIATOR CORE,UPPER LH        |         | 1   | \$58.50         | 10%           | \$ 64.35         | REPLACE ( / )                      |                                   |
| 15                           | SUPPORT-RADIATOR CORE,UPPER RH        |         | 1   | \$58.50         | 10%           | \$ 64.35         | REPLACE ( / )                      |                                   |
| 16                           | SUPPORT-RADIATOR CORE SIDE,RH         |         | 1   | \$65.00         | 10%           | \$ 71.50         | REPLACE ( / )                      |                                   |
| 17                           | SUPPORT-RADIATOR CORE SIDE,LH         |         | 1   | \$65.00         | 10%           | \$ 71.50         | REPLACE ( / )                      |                                   |
| 18                           | AIR GUIDE-FRONT,LH                    |         | 1   | \$52.00         | 10%           | \$ 57.20         | REPLACE ( / )                      |                                   |
| 19                           | AIR GUIDE-FRONT,RH                    |         | 1   | \$52.00         | 10%           | \$ 57.20         | REPLACE ( / )                      |                                   |
| 20                           | AIR GUIDE-FRONT                       |         | 1   | \$52.00         | 10%           | \$ 57.20         | REPLACE ( / )                      |                                   |
| 21                           | AIR GUIDE-FRONT                       |         | 1   | \$52.00         | 10%           | \$ 57.20         | REPLACE ( / )                      |                                   |
| 22                           | FENDER-FRONT,LH                       |         | 1   | \$351.00        | 10%           | \$ 386.10        | REPLACE ( / )                      |                                   |
| 23                           | FENDER-FRONT,RH                       |         | 1   | \$351.00        | 10%           | \$ 386.10        | REPLACE ( / )                      |                                   |
| 24                           | PROTECTOR-FRONT FENDER,LH             |         | 1   | \$143.00        | 10%           | \$ 157.30        | REPLACE ( / )                      |                                   |
| 25                           | PROTECTOR-FRONT FENDER,RH             |         | 1   | \$143.00        | 10%           | \$ 157.30        | REPLACE ( / )                      |                                   |
| 26                           | FENDER INNER PANEL,RH                 |         | 1   | \$585.00        | 10%           | \$ 643.50        | REPLACE ( / )                      |                                   |
| 27                           | FENDER INNER PANEL LOWER CONNECTOR,RH |         | 1   | \$208.00        | 10%           | \$ 228.80        | REPLACE ( / )                      |                                   |
| 28                           | FENDER INNER PANEL,LH                 |         | 1   | \$585.00        | 10%           | \$ 643.50        | REPLACE ( / )                      |                                   |
| 29                           | FENDER INNER PANEL LOWER CONNECTOR,LH |         | 1   | \$208.00        | 10%           | \$ 228.80        | REPLACE ( / )                      |                                   |
| 30                           | HOOD                                  |         | 1   | \$520.00        | 10%           | \$ 572.00        | REPLACE ( / )                      |                                   |
| 31                           | HINGE ASSY-HOOD,RH                    |         | 1   | \$62.40         | 10%           | \$ 68.64         | REPLACE ( / )                      |                                   |
| 32                           | HINGE ASSY-HOOD,LH                    |         | 1   | \$62.40         | 10%           | \$ 68.64         | REPLACE ( / )                      |                                   |
| 33                           | INSULATOR-HOOD                        |         | 1   | \$104.00        | 10%           | \$ 114.40        | REPLACE ( / )                      |                                   |
| 34                           | MALE ASSY-HOOD LOCK                   |         | 1   | \$97.50         | 10%           | \$ 107.25        | REPLACE ( / )                      |                                   |
| 35                           | CABLE ASSY-HOOD LOCK CONTROL          |         | 1   | \$39.00         | 10%           | \$ 42.90         | REPLACE ( / )                      |                                   |
| 36                           | COWL TOP ASSY                         |         | 1   | \$299.00        | 10%           | \$ 328.90        | REPLACE ( / )                      |                                   |
| 37                           | GLASS-WINDSHIELD                      |         | 1   | \$780.00        | 10%           | \$ 858.00        | REPLACE ( / )                      |                                   |
| 38                           | DAM-RUBBER,SEALANT                    |         | 1   | \$240.50        | 10%           | \$ 264.55        | REPLACE ( / )                      |                                   |
| 39                           | RADIATOR ASSY                         |         | 1   | \$650.00        | 10%           | \$ 715.00        | REPLACE ( / )                      |                                   |
| 40                           | HOSE-RADIATOR,LOWER                   |         | 1   | \$91.00         | 10%           | \$ 100.10        | REPLACE ( / )                      |                                   |
| 41                           | HOSE-RADIATOR,UPPER                   |         | 1   | \$117.00        | 10%           | \$ 128.70        | REPLACE ( / )                      |                                   |
| 42                           | MOTOR & FAN ASSY-W/SHROUD             |         | 1   | \$546.00        | 10%           | \$ 600.60        | REPLACE ( / )                      |                                   |
| 43                           | TANK ASSY-RADIATOR RESERVOIR          |         | 1   | \$104.00        | 10%           | \$ 114.40        | REPLACE ( / )                      |                                   |
| 44                           | ALTERNATOR                            |         | 1   | \$1,820.00      | 10%           | \$ 2,002.00      | REPLACE ( / )                      |                                   |
| 45                           | HEADLAMP ASSY-RH                      |         | 1   | \$364.00        | 10%           | \$ 400.40        | REPLACE ( / )                      |                                   |
| 46                           | HEADLAMP ASSY-LH                      |         | 1   | \$364.00        | 10%           | \$ 400.40        | REPLACE ( / )                      |                                   |
| 47                           | CONDENSER & LIQUID TANK ASSY          |         | 1   | \$624.00        | 10%           | \$ 686.40        | REPLACE ( / )                      |                                   |
| 48                           | TUBE ASSY-INLET INTERCOOLER           |         | 1   | \$312.00        | 10%           | \$ 343.20        | REPLACE ( / )                      |                                   |
| 49                           | TUBE ASSY-INLET INTERCOOLER           |         | 1   | \$195.00        | 10%           | \$ 214.50        | REPLACE ( / )                      |                                   |
|                              |                                       |         |     |                 |               |                  |                                    |                                   |
|                              |                                       |         |     |                 |               |                  |                                    |                                   |
| TOTAL MATERIAL: \$ 14,223.30 |                                       |         |     |                 |               | \$ 15,645.63     |                                    |                                   |