

SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: smartoneauto@gmail.com



DATE : 08.04.21

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **PC2976R**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 08.04.21
TIME OF ACCIDENT : 13:05HRS

KDH280020097.

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL LAMP <i>cut</i>	2	\$ 390.00	\$ 780.00
2	TAILLAMP LOWER GARNISH <i>Regis</i>	2	\$ 167.00	\$ 334.00
3	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 65.00	\$ 130.00
4	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00
5	REAR BUMPER BRACKET <i>Best</i>	4	\$ 21.20	\$ 84.80
6	TAILGATE <i>Distorted.</i>	1	\$ 2,054.30	\$ 2,054.30
7	TAILGATE LOGO <i>new</i>	1	\$ 75.20	\$ 75.20
8	TAILGATE EMBLEM 'HIACE' <i>new</i>	1	\$ 59.00	\$ 59.00
9	TAILGATE EMBLEM 'GL' <i>new</i>	1	\$ 69.20	\$ 69.20
10	TAILGATE CENTER MOULDING (CHROME) <i>new could</i>	1	\$ 674.80	\$ 674.80
11	TAILGATE LOCK OUTER HANDLE <i>new</i>	1	\$ 465.10	\$ 465.10
12	TAILGATE STOPPER <i>new</i>	1	\$ 28.00	\$ 28.00
13	TAILGATE INNER TRIM <i>could</i>	1	\$ 271.80	\$ 271.80
14	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 395.00	\$ 395.00
15	TAILGATE WEATHERSTRIP PROTECTOR <i>new could</i>	1	\$ 485.20	\$ 485.20
16	TAILGATE INNER LOCK <i>changed</i>	1	\$ 475.60	\$ 475.60
17	TAILGATE LOWER LOCK <i>changed new</i>	1	\$ 45.20	\$ 45.20
18	TAILGATE DAMPER <i>new new</i>	2	\$ 127.40	\$ 254.80
19	TAILGATE LOWER CORNER GARNISH <i>new</i>	2	\$ 19.60	\$ 39.20
20	TAILGATE KEY LOCK <i>new</i>	1	\$ 294.70	\$ 294.70
21	REAR END PANEL (INNER) <i>Regis</i>	1	\$ 1,043.20	\$ 1,043.20
22	REAR END PANEL (OUTER) <i>Distorted.</i>	1	\$ 597.00	\$ 597.00
23	REAR END PANEL (EXTEND) RH <i>Distorted</i>	1	\$ 362.10	\$ 362.10
24	REAR FLOOR PANEL <i>Regis</i>	1	\$ 1,888.90	\$ 1,888.90
25	REAR FLOOR PANEL MAT <i>new new</i>	1	\$ 1,591.50	\$ 1,591.50
26	REAR SPARE TYRE BRACKET <i>2 NP</i>	1	\$ 398.70	\$ 398.70
27	REAR SPARE TYRE BOLT <i>new</i>	1	\$ 104.20	\$ 104.20

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : PC2976R
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 08.04.21
 TIME OF ACCIDENT : 13:05HRS

28	REAR EXHAUST PIPE	1	\$ 874.20	\$ 874.20
29	REAR EXHAUST GASKET	1	\$ 57.80	\$ 57.80
30	REAR EXHAUST MOUNTING	1	\$ 28.10	\$ 28.10

5682.1
 4261.57

TOTAL PRICE \$ 14,071.60
 LESS 25% \$ 3,517.90
SUB TOTAL PRICE \$ 10,553.70

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER (SPECIALTYPE) <i>Distorted</i>	1	\$ 2,400.00	\$ 2,400.00
4	REAR BUMPER REFLECTOR (SET) (SPECIAL TYPE) <i>could</i>	1	\$ 380.00	\$ 380.00
5	REAR BUMPER 'A-STAR' EMBLEM (SPECIAL TYPE) <i>new</i>	1	\$ 80.00	\$ 80.00
6	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
7	TAILLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
8	TAILGATE CENTER MOULDING (CHROME) CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
9	TAILGATE LOWER CORNER GARNISH CLIP (SET) <i>new new</i>	1	\$ 50.00	\$ 50.00
10	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
11	TAILGATE STICKER '80/90 LEBUHRAYA'KM/J' (SPECIAL TYPE) <i>new</i>	1	\$ 80.00	\$ 80.00
12	TAILGATE WINDSCREEN SEALANT <i>2 new</i>	1	\$ 80.00	\$ 80.00
13	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
14	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 30.00	\$ 30.00
15	TAILGATE STICKER 'EMERGENCY EXIT' <i>new</i>	1	\$ 60.00	\$ 60.00
16	REAR END PANEL (INNER) SEALANT <i>new new</i>	1	\$ 150.00	\$ 150.00
17	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
18	REAR END PANEL (EXTEND) SEALANT <i>new new</i>	1	\$ 150.00	\$ 150.00
19	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00
20	REAR SPARE TYRE <i>new new</i>	1	\$ 350.00	\$ 350.00
21	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 220.00	\$ 220.00
22	REVERSE CAMERA <i>new new</i>	1	\$ 480.00	\$ 480.00

1620

TOTAL \$ 5,440.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,800.00	1000
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	800

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC2976R**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 08.04.21
 TIME OF ACCIDENT : 13:05HRS

3	WIRING, BULB CHECKING	\$	180.00	30.
4	TRANSFER TAILGATE MECHAISM	\$	80.00	/
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$	120.00	/
6	CONDUCT WATER LEAKAGE TEST	\$	120.00	X.
7	REMOVE AND REFIX REAR EXHAUST PIPE	\$	180.00	X.
8	REAR CHASSIS ALIGHMENT	\$	250.00	X.
9	REMOVE AND REFIX REAR REVERSE CAMERA	\$	80.00	50.
10	REMOVE AND REFIX REVERSE SENSOR	\$	80.00	50.
11	REMOVE AND REFIX LINING & SEATS	\$	480.00	X. 2130
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00	X

TOTAL \$ **5,350.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,993.70
 TOTAL LABOUR COST : \$ 5,350.00
 TOTAL REPAIR COST : \$ 21,343.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj
 w/s 09/04/21.

09 Days

09 Days. ✓

Total: 8011.57

L/s: 6 AK ✓