

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

Loh Hsiao Tony

12-06-21

Accident Date : 05-04-2021

OUR REF : SGM 6819P/T/21

Chong Chai Shen

Blk 288A Bukit Batok Street 25

#10-228

Singapore 733787

*Not Authorized
Loh*

P/P \$400

1 day

Take photo After repair

ESTIMATE BILL ON VEH. NO. : SGM 6819P

VEH. MODEL : MAZDA 3

CHASSIS NO: JM6BM42A8G0335643

LIST ITEM

Front Bumper Fascia

1 958.10 X

Front Bumper Side Retainer - RH

1 18.70 X

Front Bumper Side Attachment - RH

1 28.10 X

Fog Lamp Cover - RH

cur/nlc 46.40 X

1,051.30

Less Discount 20%:

210.26

841.04

LABOUR CHARGE

To Respray Affected Areas.

550.00 *200*

To Renew Damaged Parts, Straighten & Repair & Aligned All Parts.

500.00 *200*

1,891.04

GST 7%:

132.37

TOTAL AMOUNT :

2,023.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: