

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA4163L

Make : HYUNDAI

Model : IONIQ(G3)

Date: 05/04/21

Insurance: NTUC

MVA: JUMANI

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			del \$459.40
10	REAR BUMPER CLIPS			del \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			del \$451.25
1	REAR LICENCE PLATE LAMP LH			del \$85.30
1	REAR LICENCE PLATE LAMP RH			del \$85.30
1	REAR BUMPER LOWER CTR MOULDING			del \$155.00
1	REAR BUMPER FOG LAMP			del \$201.50
1	REAR BUMPER TOWING COVER			del \$98.80
SUB TOTAL			1087.65	\$1,558.55
LESS 20%			870.12	\$311.71
DISCOUNTED TOTAL				\$1,246.84
1	REAR NUMBER PLATE			del \$25.00
1	REAR BUMPER REVERSE SENSOR			del \$180.00
Labour Charge			25	\$205.00
PANEL BEATING			350	\$500.00
SPRAY PAINTING CHARGE			250	\$300.00
WIRING CHARGE			un \$50.00	
REMOVE/REFIX REVERSE SENSOR			30	\$120.00
TOTAL LABOUR			630	\$970.00
ESTIMATE TOTAL			1525.12	\$2,421.84
			4/5/2000	
			02 days	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 9741544
WP' 6/4/21 @ 220pm
02 days
4/5 resurvey after repair
Tanpin c/llhant in n