

CAB PTE LTD

AIR ESTIMATE\*

VEHICLE NO SHC2292C SHC 2291C

28/09/20

MAKE :  
MODEL IONIQ G3

CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT FENDER RETAINER RH/LH		RHX \$41.40	\$82.80
1	FRONT FENDR LH		nm	/\$588.80
1	FRONT FENDER BLUE DRIVE EMBLEM			/\$26.60
1	FRONT FENDER LH SHIELD			\$164.70
1	FRONT BUMPER COVER			/\$430.90
1	FRONT BUMPER BRACKET TOP RH/LH		RHX \$35.00	\$70.00
1	DAY LIGHT LH			\$642.50
10	FRONT BUMPER CLIPS		2 \$2.20	20 \$22.00
1	FRONT BUMPER MOULDING			\$318.80
1	FRONT BUMPER GRILLE /LH			\$186.20
1	FRONT SUPPORT PANEL			\$949.30
1	FRONT HEADLAMP ASSY /LH		3406.35	/\$1,993.65
1	FRONT WHEEL COVER LH		2725.08	/\$346.40
SUB TOTAL				\$5,822.65
20.00%				\$1,164.53
DISCOUNTED TOTAL				\$4,658.12
1	TYRE FRT LH			\$216.00
				\$194.40
Labour Charge				
Panel Beating				
Spray Painting Charge				
Reset wheel alignment				\$960.00
Towing Fee				\$600.00
Check Wiring				\$90.00
Tuff kote				\$90.00
				\$60.00
				\$60.00
TOTAL LABOUR				\$1,860.00
ESTIMATE TOTAL				\$3870.08
				# 3 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: 1145  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tarfon 97495749  
wp' 7/4/21 c 4pm  
1/5 Resurvey after repair  
Tarfon @ Chuanbun  
2020