

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719

E mail : xinyaauto@singnet.com.sg

Tel 6270 3481 Fax: 6278 7522

Date : 08-Apr-21

Address : TODDS PARTNERS PTE LTD
BLK 1002 BUKIT MERAH LANE 3
#01-75
SINGAPORE 159719

Reference : TP 1280/04/21
Vehicle No : SJL552S
Make/Model : TOYOTA WISH
Insurance Co. : CHINA TAIPING

Steve (LKK) WZ PL
L/S, 4 days
12/4/21, 11:30 am
By AL SH

8322 8813

RE : QUOTATION TO SJL 552S FOR THIRD PARTY CLAIMS.

PARTS REQUIRED	QTY	AMT \$
1) FRONT BUMPER ? (Amort) X R	1	\$ 986.70
2) FRONT BUMPER RETAINER ? BR	1	\$ 59.30
3) FRONT BUMPER CLIPS — MK	10	\$ 55.00 30
4) HEADLAMP — CM	1	\$ 849.31
5) FRONT FENDER LH — 00	1	\$ 611.47
LIST PRICE TOTAL		\$ 2,561.78
LESS DISCOUNT 25%		\$ 640.45
LIST PRICE TOTAL AFTER LESS		\$ 1,921.34
NETT PRICE TOTAL		\$0.00

1550.08
- 25%
1162.56

TOTAL PARTS COST

\$1,921.34

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, HEADLAMP, FENDER AND TO PANEL BEAT & ALIGN.	\$ 800.00 400 (4 DAYS)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER, FENDER AND OTHER AFFECTED AREA.	\$ 400.00 (2 PANEL)
3)	TO CHECK WRING & FOCUS HEADLAMP	\$ 100.00 30
4)	TUFF KOTE	\$ 150.00 30

LABOUR TOTAL

\$ 1,450.00

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before repair
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL ESTIMATED REPAIR COST

\$ 3,371.34

860
= 2022.56
L/S - 1618.04
= 1600