

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0288/2021/HR
DATE : 6-Apr-21
WIP : 22046

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LI HONGTAO
ADDRESS :
SINGAPORE 347470
TELEPHONE : HP +65 90685172
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SKU 3039 D**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 23/9/2019
ENGINE NO : CYR 091525
CHASSIS NO : WAUZZZ4M9KD032971
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Apr-21
PLACE OF ACCIDENT : NEAR PEOPLE PARK COMPLEX CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 3039 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓ ✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	X ,
3	TO RENEW REAR WINDSCREEN TO FACILLITATE REAR LID RENEWAL.	S/N \$	480.00	X ,
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	X ,
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00 150	✓
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,700.00 600	✓
SUB TOTAL LABOUR CHARGES		: \$	4,620.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 3039 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS.	\$ 4,000.00	2200 ✓ 600 x 3 = 1800 Wheel Arch Trim = 200 x 2 = 400
8	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$ 280.00	✓ ✓
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ <u>9,092.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 3039 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER <i>Del'd</i>	1	\$ 1,362.00	✓ 1089.60
2	REAR BUMPER - MIDDLE <i>Del'd.</i>	1	\$ 2,070.00	✓ 1656
3	REAR BUMPER FIXING PARTS <i>Not in</i>	2	\$ 208.00	X
4	REAR BUMPER LOWER SPOILER <i>Del'd</i>	1	\$ 1,261.00	✓ 1008.80
5	REAR BUMPER LOWER SPOILER TRIM <i>Not in</i>	1	\$ 107.00	X
6	REAR BUMPER CARRIER <i>Not in</i>	1	\$ 1,417.00	X
7	REAR BUMPER HOLDING STRAP <i>Not in</i>	1	\$ 182.00	X
8	REAR BUMPER GUIDE SECTION - CENTER <i>Not in</i>	1	\$ 142.00	X
9	REAR BUMPER SEAL - LH / RH <i>Not in</i>	2	\$ 28.00	X
10	REAR BUMPER GUIDE SECTION - LH / RH <i>Not in</i>	2	\$ 126.00	X
11	REAR PARKING AID SENSOR <i>Not in</i>	2	\$ 488.00	X
12	REAR PARKING AID SENSOR SEAL RING <i>Not in</i>	1	\$ 14.00	X
13	REAR BOOT LID <i>Repair</i>	1	\$ 6,018.00	X
14	REAR BOOT LID ATTACHMENT PARTS <i>Not in</i>	1	\$ 344.00	X
15	REAR BOOT LID LOCK <i>Not in</i>	1	\$ 248.00	✓
16	REAR BOOT COVER CAP <i>Not in</i>	1	\$ 13.00	X
17	REAR BOOT GASKET <i>Not in</i>	1	\$ 292.00	X
18	REAR BOOT PACKING ADHESIVE <i>Not in</i>	1	\$ 19.00	X
19	"AUDI" EMBLEM <i>Not in</i>	1	\$ 138.00	✓ 110
20	"Q7" EMBLEM <i>Not in</i>	1	\$ 99.00	✓ 71.04
SUB TOTAL SPARE PARTS		:	\$ 14,576.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 3039 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	"QUATTRO" EMBLEM <i>new</i>	1	\$ 99.00	✓ 79.04
22	REAR WINDOW <i>new</i>	1	\$ 1,174.00	+
23	PRIMER <i>new</i>	1	\$ 20.00	+
24	REAR WINDOW SIDE SPOILER - LH / RH <i>new</i>	2	\$ 462.00	+
25	REAR LID SPOILER FIXING PARTS <i>new</i>	1	\$ 62.00	+
26	REAR BUMPER TAILLIGHT- RH <i>ambd.</i>	1	\$ 359.00	✓ 286.80
27	REAR WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 754.00	✓ 602.40
28	FRONT WING MIRROR MOUNTING - RH <i>nt</i>	1	\$ 1,508.00	✓ 1206.40
29	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$ 200.00	+
30	SUNDRIES <i>Nec.</i>		\$ 250.00	✓ 14.88
TOTAL SPARE PARTS		:	\$ 19,464.00	
TOTAL LABOUR CHARGES		:	\$ 9,092.00	
GRAND TOTAL		:	\$ 28,556.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *08/04/21.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 05 Days,*
H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT