



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Admin
LKL
Adv C/P

09/04/2021

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP Chim.
Ashes.

Accident date:

Estimated repair cost for vehicle no: SMM3265K Mercedes Benz

CHASSIS: WDD2130802A654840. 2019 June.

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Head Lamp <i>wt</i>		(\$5,189.00) 3337
2	1	Front L/H Head Lamp Panel		\$453.10 X
3	1	Front L/H Head Lamp Panel Lock		\$341.60 X
4	1	Front L/H Head Lamp Lower Bracket		\$136.40 X
5	1	Front Bumper <i>deformed</i>		\$1,520.00 ← 1385
6	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
7	1	Front L/H Bumper Side Retainer <i>dash</i>		\$75.00 ✓
8	1	Front Bumper Number Plate <i>3 NP</i>		\$50.00 X
9	1	Front Bumper Towing Cover <i>new</i>		\$98.00 X
10	1	Front Bumper Lower Center Garnish <i>the new</i>		\$215.00 X
11	1	Front L/H Bumper Fog Lamp Cover <i>deformed</i>		\$60.00 ✓
12	1	Front L/H Bumper Fog Lamp Cover Chrome <i>the new</i>		\$105.00 X
13	3	Front Bumper Inner Foam <i>crushed LH</i>	\$56.00	\$168.00 56.
14	1	Front Bumper Reinforcement <i>3 NP</i>		\$348.70 X
15	2	Front Bumper Reinforcement Bracket <i>new</i>		\$146.40 X
16	1	Front L/H Fender <i>Dented</i>		\$1,088.00 ✓
17	1	Front L/H Fender Cowling <i>deformed</i>		\$217.00 ✓
18	8	Front Fender Cowling Clip <i>new</i>	\$6.50	\$52.00 30
19	1	Front R/H Lower Arm		\$622.00 X
20	1	Front L/H Stabilizer Bar		\$462.00 X
21	1	Front R/H Knuckle Arm		\$1,344.00 X
22	1	Front R/H Knuckle Arm Bearing		\$862.00 X
23	1	Front R/H Shock Absorber		\$1,386.00 X
24	1	Front L/H Shock Absorber Mounting		\$225.00 X
25	1	Front L/H Rim <i>wt</i>		\$1,080.00 ✓ (50)
26	2	Front L/H Tyre <i>the new</i>		\$400.00 X

7358
6622.20

Subtotal:- \$16,709.20

Labour charges

To check wiring	\$100.00	30
To remove & renew RH front undercarraige	\$300.00	X
To conduct all wheel alignment	\$300.00	80
Panel beating	\$1,600.00	400
Spray painting	\$1,400.00	400
Subtotal:-	\$3,700.00	
Total:-	\$20,409.20	

Q10

Total: 7532.20
L/s: GK
05 Days.

GK
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: