

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21004580/KTF3E2

Date: 07/05/2021

REFERENCE

Insured/Claimant: ASRANI MAHESH MANOHARLAL Policy No: MPC20P00052100
Date of Loss: 08/04/2021 Nature of Claim: OD Claim No: DMPC2100123H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS6974U**
Make & Model: LEXUS ES250, 2.5 (A) Engine No: 2ARF000898
Reg. Date: 30/04/2015 (Man. Year: 2015) Chassis No: JTHBJ1GG602077814
Colour: Metallic Grey Odometer: 80683 km
Engine Capacity: 2494 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 1 mm Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 1 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,735.80	1,735.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,460.00	140.00	8.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,335.80	3,195.80	140.00	4.20
+ GST 7.00/7.00% (S\$)	233.51	223.71	9.80	4.20
Nett Amount (S\$)	3,569.31	3,419.51	149.80	4.20

INSPECTION

Date of Assignment: 09/04/2021 Present Location: Alan's United Auto Pte Ltd (HQ)
Date Inspected: 12/04/2021 Inspected At: Alan's United Auto Pte Ltd (HQ)
Estimated Period of Repair: 5.0 days Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2021)
Parts:	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS6974U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR (WCP)	Bent	610.00 F	*610.00 F
2	1		*FRONT LH DOOR FRAME TAPE (REAR) (WCP)	Necessary	32.00 F	*32.00 F
3	1		*FRONT N/S DOOR FRAME TAPE (TOP) (WCP)	Necessary	40.00 F	*40.00 F
4	1		*REAR LH DOOR (WCP)	Bent	610.00 F	*610.00 F
5	1		*REAR LH DOOR FRONT RUBBER (WCP)	Cut	55.00 F	*55.00 F
6	1		*REAR LH DOOR LOWER TAPE (GUARD) (WCP)	Necessary	30.00 F	*30.00 F
7	1		*REAR LH DOOR FRAME TAPE (FRONT) (WCP)	Necessary	38.00 F	*38.00 F
8	1		*REAR LH DOOR FRAME TAPE (TOP) (WCP)	Necessary	38.00 F	*38.00 F
9	2		*REAR LH DOOR HINGE (WCP)	Bent	96.00 F	*96.00 F
10	1		*REAR LH FENDER ARCH TAPE (WCP)	Necessary	29.00 F	*29.00 F

F=Franchise part.

Sub Total (S\$)	1,578.00	1,578.00
+ Margin on L,N Items 10.00/10.00% (S\$)	157.80	157.80
Total Parts (S\$)	1,735.80	1,735.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY REPLACED AND REPAIR PARTS	New	1,000.00	900.00
2	TO REMOVE DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	600.00	560.00
Gross Labour Cost (\$)			1,600.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >