

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Apr 2021)
 Parts: 143 LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Alan's United Auto Pte Ltd/SKS6974U/09/04/2021 16:14
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT LH DOOR	0.00	0.00	Bj *610.00 F ✓
2	1		*FRONT LH DOOR FRAME TAPE (REAR)	0.00	0.00	na *32.00 F ✓
3	1		*FRONT N/S DOOR FRAME TAPE (TOP)	0.00	0.00	na *40.00 F ✓
4	1		*REAR LH DOOR	0.00	0.00	Bj *610.00 F ✓
5	1		*REAR LH DOOR FRONT RUBBER	0.00	0.00	na *55.00 F ✓
6	1		*REAR LH DOOR LOWER TAPE (GUARD)	0.00	0.00	na *30.00 F ✓
7	1		*REAR LH DOOR FRAME TAPE (FRONT)	0.00	0.00	na *38.00 F ✓
8	1		*REAR LH DOOR FRAME TAPE (TOP)	0.00	0.00	na *38.00 F ✓
9	2		*REAR LH DOOR HINGE	0.00	0.00	Bj *96.00 F ✓
10	1		*REAR LH FENDER ARCH TAPE	0.00	0.00	na *29.00 F ✓

F=Franchise part.

Sub Total (S\$) 1,578.00
 + Margin on L,N Items 10.00% (S\$) 157.80
 Total Parts (S\$) 1,735.80

Alan's United Auto Pte Ltd/SKS6974U/09/04/2021 16:14. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Not Whited
 Pulver B4 pain

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TO PUTTY AND SPRAY REPLACED AND REPAIR PARTS

New

1,000.00

2 TO REMOVE DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS

New

500/ 600.00

Gross Labour Cost (\$\$)

1,600.00

Alan's United Auto Pte Ltd/SKS6974U/09/04/2021 16:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >