



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD Ref: CS/MSG21004587/Gtf3
 4 SHENTON WAY #21-01,SGX CENTRE 2 Date: 12/04/2021
 SINGAPORE 068807 Code: MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	WC 6103J	Veh. Inspected	GBD 3594M
Policy No.	1001379622	Coverage (\$)	0.00
Claim No.	255453	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY MEI LING)	Assign Date	12/04/2021

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/03/2021	Inspection Date	12/04/2021
Survey held at	24 SUNGEI KADUT ST 4, 729050 Sungei Kadut		
Repairer	LYS ENGINEERING		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.