



Xin Yun Auto Private Limited
辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SK2919R Hyundai

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy / DD - DR	\$ 850.00 ✓
2	1	Rear bumper left bracket ? - DR	\$ 68.00 ✓
3	1	Rear bumper right bracket ? - DR	\$ 68.00 ✓
4	1	Rear bumper left retainer ? X NM	\$ 65.00
5	1	Rear bumper right retainer ? X NM	\$ 65.00
6	1	Rear bumper tow cover X NM	\$ 88.00
7	2	Bumper side cover ? (RH) - CRU	\$ 220.00 80 ✓
8	1	Bumper lower lip - CRU ? X NM	\$ 685.00 ✓
9	1	Bumper lower side support ? X NM	\$ 225.00
10	1	Bumper lower side support ? X NM	\$ 225.00
11	1	Bumper lower trim ? X NM	\$ 258.00
12	1	Rear tailgate rubber garnish X NM	\$ 372.20
13	1	Rear reinforcement X - BR	\$ 676.30 488 ✓
14	1	Rear boot assy + R	\$ 995.00
15	1	Boot lid outer garnish X NM	\$ 225.60
16	1	Rear tailgate emblem X NM	\$ 85.00
17	1	Rear tailgate weatherstrip - TN	\$ 275.00 148 ✓
18	1	Rear boot lock mechanism + NM	\$ 280.00
19	1	Boot lower lock cover X NM	\$ 48.00
20	1	Rear tailgate inner trim board X NM	\$ 375.00
21	1	Tailgate internal board X NM	\$ 350.00
22	1	Rear fender trim left (inside boot) X NM	\$ 425.00
23	1	Rear fender trim right (inside boot) X NM	\$ 425.00
24	1	Pull pocket / on bonnet X NM	\$ 88.00
25	1	Rear tailgate no plate lamp X NM	\$ 65.00
26	1	Bumper lower light left X NM	\$ 225.00
27	1	Bumper lower light right X - CRU	\$ 225.00 ✓
28	1	Rear left taillamp X NM	\$ 695.00
29	1	Rear right taillamp X NM	\$ 695.00
30	2	Rear tailgate damper / impact big got sounds X NM	\$ 400.00
31	1	Rear end lower panel / bent badly ? X R	\$ 580.00
32	2	Edge molding / middle panel ? X NM	\$ 220.00
33	1	Rear end tool box big cover X NM	\$ 385.00
34	1	Top tool board X NM	\$ 550.00
35	1	Floor panel control / spare tyre panel X NM	\$ 585.40
36	1	Rear quarter panel left X NM	\$ 325.00
37	1	Rear quarter panel right X NM	\$ 325.00
38	1	Rear end lower panel top garnish ? X NM	\$ 225.00
39	1	Rear exhaust cover X NM	\$ 195.00
40	1	Rear exhaust muffler assy X NM	\$ 680.00
41	3	Rear exhaust muffler mounding X NM	\$ 90.00
42	1	Antena, electrical key ? X NM	\$ 185.00
			\$ 14,087.50

2612
-20%
2089.60



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

✓
SK2919R Hyundai

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips — MK ? X NN	\$ 80.00 30 ✓
2	6	Rear end lower panel top garnish clips ? X NN	\$ 50.00
3	1	Rear end lower panel sealant ? X NN	\$ 120.00
4	8	Rear tailgate inner trim board clips X NN	\$ 50.00
5	6	Rear tailgate outer garnish clips X NN	\$ 50.00
6	1	Rear floor panel insulator pad X NN	\$ 150.00
7	1	Rear floor panel sealant X NN	\$ 120.00
8	1	Rear windscreen glass sealant X AK NN	\$ 80.00
9	3	Rear windscreen mounding X AK NN	\$ 320.00
10	2	Rear bumper reverse sensor — SL	\$ 250.00 770 ✓
11	1	Rear no plate with garnish — OT	\$ 80.00 45 ✓
12	1	Number plate setting X NN	\$ 105.00
13	2	inner coating protection — MK	\$ 30.00 /
14	1	PU420 black / car body waterproof — MK	\$ 45.00 30 ✓

335



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SK 2019R Hyundai

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area	\$ 2,000.00	400 600
2	To putty and spray painting rear portion.	\$ 1,800.00	400 600
3	To check rear lighting and wiring.	\$ 50.00	30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	50 X
5	To remove & install rear windscreen glass to facilitate the repair.	\$ 150.00	100 X
6	To apply anti rust proofing to rear affected area including behind snare tyre area	\$ 250.00	30
7	To remove and install rear end panel	\$ 120.00	10 X
8	To remove and install rear bumper reverse sensor.	\$ 80.00	30
9	To remove and install rear exhaust muffler assy.	\$ 120.00	X
10	To remove and interal side fender trims to facilitate the repair	\$ 180.00	X
11	To remove the ceiling to facilitate the repair	\$ 250.00	X
12	To remove and install rear camera	\$ 80.00	30
13	To remove the behind windscreen to facilitete change boot	\$ 150.00	X
14	To remove boot middle glass panel to facilitate the repair	\$ 120.00	X
15	To remove both side roof side panel, adjust the squeeze and dent	\$ 250.00	X
Total labour :		\$ 5,680.00	1320

Steve CLKK

14/4/21, 1.30pm

Wil PL

L/S

My PL SLJ

4 dys

Total parts : 15,617.50

Total labour : 5,680.00

Total repair cost : 21,297.50

P-2089.60

M-335

L-1320

3744.60

L/S-2995.68

= 3000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: