



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

09/04/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA.

Xiao Tong

Accident date: 08/04/2021

Estimated repair cost for vehicle no: SLK2016S MERCEDES BENZ GLC250 4MATIC 1

CHASSIS: WDC2539462F169748

S/n	Qty	Items / Nett	U/price	Amount
1	1	Rear Bumper <i>torn</i>		\$940.00
2	1	Rear Bumper Lower <i>torn</i>		\$540.00
3	1	Rear R/H Bumper Side Retainer <i>new</i>		\$128.00
4	1	Rear R/H Bumper Side Reflector <i>new</i>		\$165.00
5	1	Rear Bumper Lower Chrome <i>new</i>		\$386.00
6	1	Rear R/H Tail Lamp <i>lit</i>		\$650.00
7	1	Rear R/H Tail Lamp Bracket <i>new</i>		\$165.00
8	1	Rear R/H Fender <i>2 not</i>		\$2,100.00
9	1	Rear R/H Fender Air Vent <i>new</i>		\$127.00
10	1	Rear R/H Fender Arch Protector <i>lit</i>		\$280.00
11	8	Rear R/H Fender Arch Protector Clip <i>new</i>	\$6.50	\$52.00
12	1	Rear Exhaust Aluminium Shield <i>new</i>		\$238.00
13	1	Rear R/H Rim <i>lit</i>		\$1,620.00

Subtotal :- \$7,391.00

Labour charges

To remove & refit reverse sensor

\$100.00 *50*

To check wiring

\$100.00 *30*

Panel beating

\$1,200.00 *200*

Spray painting

\$1,200.00 *200*

2175

1957.50

S.N. 11000

480

Subtotal:- \$2,600.00

Total:- \$9,991.00

total: 3437.50

2/s: 2.7K.

03 Days

2.7K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: