

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

9-Apr-21

Our ref : TP/4970/21

HockHua Tonic Pte Ltd

TP AIG.

Xiao Tony

RE : estimate cost for vehicle no : GBE 8469D

1 pc	rear lh door	Repair	\$	1,469.60	nett +
1 pc	NV 200 emblem	new		141.70	✓
1 pc	Nissan emblem	new		64.90	✓
1 pc	rear lh door lock lower	Dented		115.00	✓
1 pc	rear lh door w/strip	new cut		111.00	✓
1 pc	rear rh door	Repair		1,102.00	+
1 pc	DCI emblem	new		136.30	✓
1 pc	rear bumper	Dented		632.70	✓
2 pcs	rear bumper reflector	new		123.80	+
10 pcs	rear bumper clips	new		51.00	✓
1 pc	rear bumper sponge	cut		94.00	✓
2 pcs	rear bumper retainer	new		84.00	✓
1 pc	end panel outer	Dented		511.00	✓
				4,637.00	
				463.70	
				4,173.30	
1 pc	Co logo	new		400.00	nett 200.
1 pc	70km/h sticker	new		25.00	15
1 pc	6 pax sticker	new		25.00	15
1 pc	reverse sensor	Damaged		250.00	200.
1 pc	rear lh door glass	gum		40.00	+
1 pc	rear rh door glass	gum		40.00	+
Panel beating.				1000.00	600
Spray painting.				1000.00	600
Transfer 2 doors parts.				100.00	x
Remove & refit rear lh door glass.				100.00	x
Remove & refit rear rh door glass.				100.00	+
				7253.30	
				507.73	
				7761.03	

less 10%

Plus 7% GST

SD : Seven thousand seven hundred sixty-one & cents three only.

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian L;
L/s 09/04/21
05 Days
Total: 3377.44
L/s: 2.7K