

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 13 Apr 2021

**Preliminary Advice**

Insured Vehicle No	: GBB9193H	Accident Date	: 01/04/2021
TP Vehicle No	: GBG1925P	Assignment Date	: 12/04/2021
Make	: TOYOTA HIACE	Est. Duration of Repair	: 5
Date of Inspection	: 12/04/2021		
Inspection At	: BH AUTO SERVICES PTE LTD (SIN MING) BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C, #01/111/113/115/117 SINGAPORE 575636		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,342.50
Revised Amount	:S\$	2,476.50
Check Items (Estimated)	:S\$	2,591.50
Total	:S\$	5,068.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :