

ASS. REG. BY:

REF:

CS/EG121004601/Kqf3

21004601/Kq

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / P / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: GBG 1925P

at Workshop m/s: B1H

of _____

Insured: GBB 9193H

Policy No. _____

Claims No. CDMCG21000625-001


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBG 1925P Yr Regn: 06.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota cc 2982

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 130731 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size: F: 195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 1/4/21

Rear

R/Bal. 4 mm

L/Bal. 4 mm

D.O.I. 12/4/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/4/2021 @ 1.54PM	REVISED TO ERGO VIA MERIMEN.

Kenneth confirmed LS \$2300 (Red \$6042.50, 72%)

Data/Time, File Pass to?

☐ : Prell. Report

11/03/08 Typist

☐ : Final Report

Data/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Fees

Others

TOTAL

Report Format: MER-TP

Lump Sum: \$2300

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

EGRO Insurance Pte Ltd
9 Temasek Boulevard
#04-01 Suntec Tower 3
Singapore 038988
ATTN: MOTOR CLAIM DEPARTMENT

Not Authorized
Lily B
Account After Paying

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: GBG1925P
MODEL : TOYOTA HIACE SUPERGL
POLICY NO :
CHASSIS NO : KDH2010222383
ENGINE NO : 1KD2708864
DATE / TIME OF ACCIDENT: 1 April 2021 at 1814hrs along Jln Eunus
THIRD PARTY VEHICLE NO: GBB9193H

Date: 8/4/2021
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts	Quantity	Unit Price	Condition	Amount
S/N		SS		SS
1 REAR TAILGATE				By 1,441.00 ✓
2 REAR TAIGATE GLASS PANEL				By 651.00 X
3 REAR TAIGATE GLASS PANEL WEATHER STRIP				By 395.00 X
4 TAILLAMP LH				By 338.00 X
5 TAILLAMP RH				By 338.00 X
6 REAR END PANEL				321.00 ✓
7 REAR BUMPER				By / Bu 400.00 ✓
8 REAR BUMPER SIDE RETAINER RH				By 65.00 X
9 REAR BUMPER SIDE RETAINER LH				By 65.00 X
10 REAR BUMPER INNER PANEL				By 851.00 X
11 REAR BUMPER STEP GARNISH				By 260.00 X
12 REAR TAILGATE LOCK SET				441.00 ✓
13 REAR BUMPER SPONGE				
14 STICKER 'HIACE'				By 86.00 ✓
15 STICKER 'SUPERGL'				By 48.00 ✓
16 STICKER TOYOTA EMBLEM				By 75.00 ✓

25% Sub-Total: 5,775.00
Less: 20% discount - 1,732.50
Total Parts after 20% discount: 4,042.50

Special Nett Items

1 Anti rust coating	1	80.00	By 80.00 301
3 Rear license plate and casing	1	120.00	By 120.00 X
4 Reverse sensor set	1	250.00	250.00 ✓
5 Rear bumper reflector sticker	2	25.00	By 50.00 X
6 70KM sticker	1	35.00	By 35.00 120

7	8 pax sticker	1	35.00	125m	35.00
8	Windscreen sealant	1	120.00	40m	120.00
9	Rear end panel seal	1	120.00	7	120.00
					<u>810.00</u>

Total Parts: 4,852.50

Labour Charges For Front & Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,500.00	7
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,200.00	600
3	Provide skill labour to remove and replace bumper sensor	120.00	50
4	Provide skill labour to disconnect and check electrical wiring	100.00	15
5	Provide skill labour to remove and refit rear end panel lining and garnish to facilitate repair	150.00	7
6	Provide skill labour to check and re-adjust wheel alignment	100.00	x
7	Provide skill labour to dismantle and transfer tailgate fitting to new/facilitate repair	120.00	60
8	Provide skill labour to remove and replace rear windscreen	200.00	120

Total Labour:

Total Parts & Labour:

GST 7%

Grand Total:

3,490.00

8,342.50

583.98

8,926.48

Estimate Repair Duration

5days

4-5days

ACCIDENT VEHICLE OF : GBB9193H

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/04/2021 12:50 (SGT)
Date of Accident	01/04/2021 18:14 (SGT)
Exact Location of Accident	Jln Eunus, Singapore
Additional Location Information	TOWARDS PARKWAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBG1925P

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	EMMANUEL LOGISTICS XPRESS
Company Reg No	5XXXX588D
Email Address	ERICCHUI@MAIL.COM
Mobile Phone No	(Phone) +65-92726982
Alternative Phone No	+65-92726982

2017.

98593611

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	1999

INSURANCE COMPANY

Name of Insurance Company	Etiqua Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-


DRIVER

Name of Driver	CHUI WENG KHEONG
NRIC No	SXXXX671A

SKETCH PLAN

SALAN BUNDS TOWARD PARKWAY

(A) GBB 1925P
(B) GBB 9193H



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving at Emos near traffic light. Drive slowly and stop at yellow box. Few seconds suddenly my van was hit by another vehicle behind. Vehicle no. GBB 9193H. We exchange contact details and will claim insurance. My van at rear area was damaged. The time happen at 1814 hours.

DECLARATION

I declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

1/4/2021
22.51 hours

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.: