

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO21004603/Urf3
50 RAFFLES PLACE #03-03		Date:	12/04/2021
SINGAPORE LAND TOWERS SINGAPORE 048623		Code:	SMO
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLB 4697K	Veh. Inspected	SMK 3564H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2101110/IJH	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	12/04/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/04/2021	Inspection Date	12/04/2021
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			