

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/GRB21004606/BVF3E2

**Date:** 26/04/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SJZ9868Z **Insured Vehicle No :** SMV9852D  
Date of Loss: 09/04/2021 Nature of Claim: TP Claim No: MFL2021D0001676

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ9868Z**  
Make & Model: TOYOTA VELLFIRE, 2.4 Z G-Edition (A) Engine No: 2AZH782559  
Reg. Date: 18/01/2012 (Man. Year: 2011) Chassis No: ANH208192047  
Colour: Black Odometer: 271030 km  
Engine Capacity: 2362 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/04/2021  
Date Inspected: 13/04/2021 Inspected At: T & S MOTOR SERVICE (HQ)  
BLK 5035 ANG MO KIO INDUSTRIAL PARK 2  
#01-357 .  
SINGAPORE 569538  
Estimated Period of Repair: 0.0 days

**Adjuster:** Lim Teow Guan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2021)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 Z G-Edition (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ9868Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

< END OF ESTIMATES >