

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Apr-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6766 Z

1 pc	Rear bumper	\$	696.00	RY
1 pc	Rear bumper o/s side bracket	\$	16.00	X NY
1 pc	Rear o/s fender	\$	1,205.00	RY
1 pc	Rear o/s fender inner shield	\$	120.00	X NY
1 pc	Rear windscreen moulding	\$	87.00	X NY
1 pc	Wheel cover	\$	116.00	CR
1 pc	Rear o/s shock absorber	\$	313.00	X
1 pc	Rear o/s lower arm	\$	351.00	X
1 pc	Rear o/s trailing arm	\$	159.00	X
1 pc	Rear o/s knuckle arm	\$	525.00	X
1 pc	Rear o/s hub bearing	\$	349.00	X
1 pc	Rear o/s Assist arm	\$	163.00	X
1 pc	Rear o/s rim	\$	246.00	R.P.
		\$	4,346.00	
		\$	434.60	116
		\$	3,911.40	10440

Less 10%

### S/NETT

1 set	Rear bumper clips	\$	48.00	X NY
1 set	o/s door sticker	\$	100.00	60 nec
1 pc	Rear o/s fender sticker	\$	60.00	30 nec
1 set	Rear o/s fender inner shield clips	\$	28.00	X NY

90

12-Apr-21

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6766 Z**

Sundry	\$	50.00	<sup>20</sup>
To dismantle / refit reverse sensor to new bumper and reset to the same	\$	120.00	<sup>30</sup>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	<sup>60</sup>
To check wheel alignment	\$	80.00	✓
To dismantle and replace rear o/s undercarriage	\$	180.00	<sup>150 photo</sup> X un
To dismantle and refit the rear windscreen	\$	120.00	X un
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear o/s door etc	\$	1,000.00	<sup>400</sup>
To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, o/s rocker panel garnish	\$	800.00	<sup>700</sup>
To apply rustproofing on the repaired and replaced panels.	\$	150.00	X un
	\$	<u>6,827.40</u>	<sup>1290</sup>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

205/07M5  
1484.40

Tanpin 97495749 451150  
in, 12/4/2021 550 days  
CS Resurvey after repair  
3-4 days  
tanpin@lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: