

IFORTDELGRO ENGINEERING PTE LTD

AIR ESTIMATE*

LKL

VEHICLE NO SHD3169L

DATE 12/04/21 12:00 AM

MAKE :

CHIANG/AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER		Ry	\$1,052.20
1	RADIATOR GRILLE		ny	\$1,480.00
10	BUMPER CLIP		ny	\$22.00
1	FRONT BUMPER BRACKET TOP LH/		ny	\$28.60
1	FRONT BUMPER BRACKET SIDE /LH		ny	\$28.60
	SUB TOTAL		1502	\$2,611.40
	20.00%		1201.60	\$522.28
				\$2,089.12
1	FRONT NUMBER PLATE W/HOLDER		ny	\$55.00
	Labour Charge			
	Panel Beating		280	\$600.00
	Spray painting		250	\$500.00
	Check Lighting		ny	\$50.00
	TOTAL LABOUR		530	\$1,150.00
	ESTIMATE TOTAL			\$3,239.12
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphie 47445445
wp, 12/4/21 @ 430

1786.60
458/450, 2 days

02 days
45 hours after repair
tanphie 1/11/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: