

ESTIMATE

ate No. : b1 58100
 Estimated : 09/04/2021
 ared By : Chua Kee Sin

Page No. : 2 of 6

N. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
8887U	WBA6V12070ED05447	22/11/2018	216i GT	0

DESCRIPTION

To supply and install rear left window glass solar film.

VALUE

500.00

To remove and install front suspension for inspection and replace damaged parts.

2,655.00

Sundries

150.00

Total Labour 1:

17,363.00

DESCRIPTION

QTY

PRIC

VALUE

PLUG IN RETAINER ? xnn	2	4.00	8.00
WHEEL HUB WITH BEARING ? xnn	1	511.30	511.30
FRT RH CARRIER - undercarriage ? xnn	1	486.70	486.70
Swivel bearing right ? xnn	1	551.45	551.45
ALLOY RIM 7.5X17 DOUBLE SPK 549 xnn	1	930.80	930.80
ALLOY RIM 7.5X17 DOUBLE SPK 549 xnn	1	930.80	930.80
HUB CAP WITH CHROME EDGE xnn	1	29.80	29.80
HUB CAP WITH CHROME EDGE xnn	1	29.80	29.80
FRT LH FENDER 5f ✓	1	630.25	630.25 ✓
LH EXTENSION WHEEL HOUSING STRUT ? xnn	1	170.45	170.45
LH CROSS SUPPORT SIDE PANEL ? xnn	1	32.60	32.60
LH TOP SIDE PANEL BRACKET ? xnn	1	35.30	35.30
FRT LH DOOR 5f ✓	1	1,142.60	1,142.60 ✓
RR LH DOOR 5f ✓	1	1,142.60	1,142.60 ✓
MODEL LETTERING SIDE (SPORT LINE) xnn	1	46.75	46.75
SET OF SCREWS -mirror ? xnn	1	24.70	24.70
LH OUTSIDE MIRROR COVER CAP PRIMED xnn	1	115.30	115.30
LH SUPPORTING RING - mirror xnn	1	58.95	58.95
LH LOWER HOUSING SECTION mirr xnn	1	46.10	46.10
LH EXTERIOR MIRROR W/O MOUNTING PAR see ✓	1	496.10	496.10 ✓
LH ADDITIONAL TURN INDICATOR LAMP xnn	1	59.65	59.65
LH COVERING PRIMEND xnn	1	48.00	48.00
LH DOOR OUTSIDE HANDLE CARRIER (CA) xnn	1	106.20	106.20
FRT LH DOOR BRAKE ? xnn	1	74.60	74.60
LH OUTER DOOR HANDLE PRIMED (CA/OVT) xnn	1	120.00	120.00
REAR DOOR BRAKE ? xnn	1	74.60	74.60
FRT LH DOOR INSIDE CHANNEL SEALING ? xnn	1	60.90	60.90
FRT LH DOOR WINDOW GLASS xnn	1	209.05	209.05
FRT LH DOOR EXTERIOR CHANNEL COVER xnn	1	100.30	100.30
FRT LH DOOR WINDOW FRAME COVER (ALU) xnn	1	60.50	60.50
REAR LH DOOR WINDOW FRAME COVER (AL) xnn	1	60.50	60.50
FRT LH DOOR WINDOW GUIDE xnn	1	123.20	123.20
Foam seal -1 xnn	1	22.05	22.05
Foam seal - 2 xnn	1	22.05	22.05
FRT LH WINDOW LIFTER W/O MOTOR ? xnn	1	316.65	316.65
RR LH WINDOW LIFTER W/O MOTOR xnn	1	316.65	316.65