Id	<	1	of 2 ?	>	Þ١	$\bigcirc$	<b>⊕</b>	100%	~		ф	Find   Next	
----	---	---	--------	---	----	------------	----------	------	---	--	---	-------------	--



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Aut	tomob	ile						
	AIG ASIA PACIFIC	INSURANCE PTE LTD	Re	ef:	CS3/AIG21004623/Evf3						
	78 SHENTON WAY AIG BUILDING SINGAPORE 0791		Da	ate:	12/04/2021						
			Co	ode:	AIG						
1.		Policy Particulars :-	- (THIRD PARTY CL	AIM)							
	Insured Veh.	SMS 9674S	Veh. Inspected		SMK 1830C						
	Policy No.		Coverage (\$)		0.00						
	Claim No.		Excess (\$)		0.00						
	Assign From	ERIC TEO WEI HONG	Assign Date		12/04/2021						
2.	Vehicle Particulars & Condition										
	Make & Model		c.c		0						
	Engine No.	HIDDEN	Year of Reg.								
	Chassis No.		Colour								
	Odometer	=	Steering								
	Brakes		Modification								
	General										
3.	•	Condition	ons of Tyres								
		Size	Make		Balance						
	R/H Front Tyre				mm						
	L/H Front Tyre				mm						
	R/H Rear Tyre				mm						
	L/H Rear Tyre				mm						
4.	Description of Damages										
5.			Information								
	Accident Date	09/04/2021	Inspection Date		13/04/2021						
	Survey held at										
		25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGPORE 417800.									
5a.	Remarks										
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.										