

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBF4764Y

No.	Qty	List Items		
1	1	Front bumper	\$	459.70
2	2	Front bumper side clips	\$	46.00
3	1	RH headlamp	\$	704.15
4	1	Front RH corner panel	\$	258.10
5	1 set	Front windscreen moulding	\$	110.20
6	1	Front RH door	\$	1,410.35
7	1	Front RH door rubber	\$	161.40
8	1	Front RH door inner lock	\$	509.23
9	1	Front RH door inner lock catch	\$	65.20
10	1	Front RH door inner trim board	\$	780.15
11	1 set	Front RH door inner trim board clips	\$	50.00
12	2	Front RH door hinge (Top & bottom)	\$	148.60
13	1	Front RH door checker	\$	120.45
14	1	Front RH door glass outer moulding	\$	156.56
15	1	Front RH door glass channel	\$	205.02
16	1	Front RH door pillar (Outer)	\$	435.96
17	1	Front RH door pillar rubber	\$	202.56
			\$	5,823.63
			Less 25%	\$ 1,455.91
			Total :	\$ 4,367.72

<u>Special Nett Items</u>				
18	1 set	Front windscreen sealant	\$	50.00
19	1	Front RH door lower black company sticker	\$	40.00
			Total :	\$ 90.00

<u>Labour</u>			
1	Labour Charges for remove/refit and replace damage parts	\$	1,000.00
2	To putty and spray Spray Paintings charges.	\$	1,000.00
3	To remove, refit front windscreen glass.	\$	140.00
4	To check wirings and lightings.	\$	40.00
5	To remove, refit door fittings.	\$	80.00
6	To remove, refit dashboard assy.	\$	280.00
7	To supply and apply rust proofing treatments.	\$	80.00
Total :		\$	2,620.00

Total Parts and Labour : \$ 7,077.72