



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lum Tse Meng Benny 61 Soo Chow Garden Road Singapore 575512 Contact No Mobile: 96194049	Cust No/Name /Lum Tse Meng Benny Reg No/Reg Date SKS9087K / 14/05/201 Date In/Mileage / 0 Chassis No JMYXTGF3WFZ002166 Engine No 4B12PM4096 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27) Colour/Trim U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	09/03/2021/ 10:04	QUK	282 / Kevin Leong	63779			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								755 2280.00
REPLACE FRT LH DOOR, LH AIR DAM, RR LH PANEL MOULDING & AFFECTED AREA 1 1/2 +80								
REPAIR ON REAR LH DOOR & REAR LH FENDER								1050 2200.00
E PNT98000								120 180.00
PAINT WORK ON FRT LH DOOR, REAR LH DOOR & REAR LH FENDER 3								40 150.00
E PNT88000								50.00
TO TRANSFER FRT LH DOOR ATTACHMENTS TO NEW PANEL								
M SUNDRY								
PERFORM RUST PREVENTION								
M SUNDRY								
TO APPLY SEALANT ON AFFECTED AREA								30 120.00
A 54900099								120 280.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								20 50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
SUNDRIES					1.00	1138.00	00.00	1138.00
M PANEL ASSY, FR DOOR, LH					1.00	130.00	00.00	130.00
M MLDG, F/DR WDO BELT LINE, LH					1.00	168.00	00.00	168.00
M W/STRIP, FR DR OPNG, OTR LH					1.00	47.00	00.00	47.00
M W/STRIP, F/DR OPNG, LWR LH					1.00	544.00	00.00	544.00
M AIR DAM, SIDE, LH					1.00	42.00	00.00	42.00
M TAPE, FR DOOR SASH, LH					1.00	199.00	00.00	199.00
M MOULDING, RR WHEEL ARCH, LH					1.00	106.00	00.00	106.00
M MOULDING, RR BUMPER, LH								

Estimate

Store CLKK)
12/4/21, 2.00pm
OD - NM AL
EXCISE - ?
P/P

Estimate

Steve CLKK
12/4/21, 2.00pm
00-NH AL
EXCIS - ?
P/P

Confirm & accepted by

LKK Auto Consignment notice notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

This survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

My Bel Sh
5 dfr

7% GST on 8284.00
Total Payable 8,863.88

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.