

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 12.04.2021
 Emailed : ~~18.05.2021~~, 10.30pm
 Date Survey : 12.04.2021

VEHICLE NO : SMR 7577 H
 MODEL : KIA NIRO 1.6 A SX
 WIP : 31885

Material	:	\$	<u>7,119.20</u>
Labour	:	\$	<u>5,650.00</u>
Sub-Total	:	\$	<u>12,769.20</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>12,469.20</u>
GST 7%	:	\$	<u>872.84</u>
Grand Total	:	\$	<u>13,342.04</u>
Finalise By/Date	:		<u>LOI / 20/05/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 12/04/2021	<table> <tr> <td>Cust No/Name</td><td>/KENT GOH JING KANG</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMR7577H / 10/01/2020</td></tr> <tr> <td>Date In/Mileage</td><td>12/04/2021/ 20318</td></tr> <tr> <td>Chassis/Package</td><td>KNACC81CVL5337555 /KC17P(F)+</td></tr> <tr> <td>Engine No</td><td>G4LEKS563509</td></tr> <tr> <td>Make/Model</td><td>KIA/NIRO 1.6 A SX SR ASY PE</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/KENT GOH JING KANG	Reg No/Reg Date	SMR7577H / 10/01/2020	Date In/Mileage	12/04/2021/ 20318	Chassis/Package	KNACC81CVL5337555 /KC17P(F)+	Engine No	G4LEKS563509	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/KENT GOH JING KANG														
Reg No/Reg Date	SMR7577H / 10/01/2020														
Date In/Mileage	12/04/2021/ 20318														
Chassis/Package	KNACC81CVL5337555 /KC17P(F)+														
Engine No	G4LEKS563509														
Make/Model	KIA/NIRO 1.6 A SX SR ASY PE														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	20/05/2021/ 14:23	BLK	260 / AiTing	31885			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								400.00
REPLACE FRONT DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								
E PNT88000								800.00
REPLACE REAR DAMAGED PARTS, REPLACE REAR BUMPER, TAILGATE, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								
E PNT98000								350.00
RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME								
E PNT98000								700.00
RESPRAY ON REAR BUMPER, TAILGATE, AND ALL OTHER AFFECTED AREAS TO THE SAME								
E PNT88000								120.00
REMOVE & INSTALL RADIATOR & A/COND CONDENSER TO FACILITATE REPAIR								
E PNT88000								60.00
REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								
E PNT88000								240.00
REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR								
M SUNDRY								80.00
APPLY REAR WINDSCREEN GLASS SEALANT								
E PNT88000								120.00
REMOVE & INSTALL REAR BOOT COMPARTMENT TO FACILITATE REPAIR								
E PNT88000								120.00
TRANSFER REAR TAILGATE ATTACHMENTS, LOCK, TRIMS, INNER COVER, AND ALL OTHER ATTACHMENTS TO FACILITATE REPAIR								
M SUNDRY								40.00
APPLY SEALANT ON AFFECTED AREAS								
M SUNDRY								40.00
PERFORM RUST PREVENTION ON AFFECTED AREAS								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
M SUNDRY								30.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 12/04/2021	Cust No/Name /KENT GOH JING KANG Reg No/Reg Date SMR7577H / 10/01/2020 Date In/Mileage 12/04/2021/ 20318 Chassis/Package KNACC81CVL5337555 /KC17P(F)+ Engine No G4LEKS563509 Make/Model KIA/NIRO 1.6 A SX SR ASY PE Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	20/05/2021/ 14:23	BLK	260 / AiTing	31885			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
SUNDRIES								
S	SPECIALISTJOB							✓ 100.00
	SUPPLY & REPLACE FRONT & REAR NUMBER PLATE WITH FRAME							
E	PNT88000							800.00
	REPLACE REAR END PANEL, & REPAIR REAR FLOOR PANEL							
E	PNT98000							700.00
	RESPRAY ON REAR END PANEL, & REAR FLOOR PANEL							
E	PNT88000							400.00
	REMOVE & REINSTALL FRONT SUPPORT PANEL TO FACILITATE REPAIR							
S	SPECIALISTJOB							? 80.00
	VACUUM & TOP UP A/COND GAS							
A	90000001							200.00
	BLEED HYBRID MOTOR							
E	PNT88000							120.00
	REMOVE & INSTALL REAR SEAT TO FACILITATE REPAIR							
X	EXC							-300.00
	INSURANCE EXCESS							
X	BEAM COMPLETE-FR BUMPER				1.00	✓ 661.00	20.00	528.80
X	CONDENSER ASSY-COOLER				1.00	? 639.00	20.00	511.20
X	GUARD-AIR,RH				1.00	? 29.00	20.00	23.20
X	GUARD-AIR,LH				1.00	? 29.00	20.00	23.20
X	DAM-AIR				1.00	? 27.00	20.00	21.60
X	BLOWER ASSY				1.00	? 546.00	20.00	436.80
X	COVER-FR BUMPER UPR				1.00	? 637.00	20.00	509.60
X	COVER-FR BUMPER,LWR				1.00	? 373.00	20.00	298.40
X	GRILLE ASSY-RADIATOR				1.00	✓ 441.00	20.00	352.80
X	COVER ASSY-RADIATOR GRILLE UPR				1.00	✓ 40.00	20.00	32.00
X	ABSORBER-FRONT BUMPER ENERGY				1.00	✓ 68.00	20.00	54.40
X	GRILLE-FRONT BUMPER				1.00	✓ 131.00	20.00	104.80
X	FLAP ASSY-ACTIVE AIR,LWR				1.00	✓ 481.00	20.00	384.80
X	DUCT ASSY-ACTIVE AIR				1.00	? 64.00	20.00	51.20
X	LOGO ASSY-KIA SUB				1.00	✓ 51.00	20.00	40.80
X	PANEL ASSY-BACK				1.00	? 526.00	20.00	420.80

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 12/04/2021	Cust No/Name /KENT GOH JING KANG Reg No/Reg Date SMR7577H / 10/01/2020 Date In/Mileage 12/04/2021/ 20318 Chassis/Package KNACC81CVL5337555 /KC17P(F)+ Engine No G4LEKS563509 Make/Model KIA/NIRO 1.6 A SX SR ASY PE Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	20/05/2021/ 14:23	BLK	260 / AiTing	31885			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	PANEL ASSY-TAIL GATE				1.00	✓ 1309.00	20.00	1047.20
X	EMBLEM-NIRO				1.00	✓ 25.00	20.00	20.00
X	LOGO-KIA				1.00	✓ 42.00	20.00	33.60
X	EMBLEM-ECO HYBRID				1.00	✓ 29.00	20.00	23.20
X	COVER-RR BUMPER,UPR				1.00	✓ 486.00	20.00	388.80
X	COVER-RR BUMPER LWR				1.00	✓ 392.00	20.00	313.60
X	SKID PLATE-RR BUMPER				1.00	✓ 98.00	20.00	78.40
X	COVER-RR BUMPER SIDE UNDER,LH				1.00	? 12.00	20.00	9.60
X	COVER- RR REFLECTOR, LH				1.00	✓ 51.00	20.00	40.80
X	CAP-RR HOOK				1.00	✓ 7.00	20.00	5.60
X	LAMP ASSY-REAR FOG & R/REFL,LH				1.00	✓ 364.00	20.00	291.20
X	BRACKET-RR BEAM LWR MTG,LH				2.00	? 5.00	20.00	8.00
X	BRACKET-RR RAIL LWR MTG				1.00	? 5.00	20.00	4.00
X	BEAM-RR BUMPER				1.00	✓ 261.00	20.00	208.80
X	STAY-RR BUMPER LH				1.00	? 67.00	20.00	53.60
X	STAY-RR BUMPER RH				1.00	? 67.00	20.00	53.60
X	BRACKET ASSY-RR BUMPER SIDE,LH				1.00	? 25.00	20.00	20.00
X	ULTRASONIC SENSOR ASSY-P.A.S				1.00	163 ? 189.00	20.00	151.20
X	CLIP				10.00	1.00	20.00	8.00
X	GARNISH ASSY-QTR SIDE,LH } Supp.				1.00	144.00	20.00	115.20
X	RADIATOR ASSY				1.00	? 492.00	20.00	393.60
X	RETAINER ASSY-BUMPER COVER MTG				10.00	2.00	20.00	16.00
X	SENSOR-AMBIENT } Supp.				1.00	25.00	20.00	20.00
X	COOLANT (4L)				1.00	26.00	20.00	20.80
Z TEXT								
AIG OD CLAIM, UIL CLAIM SJN1019Z								
DOA : 12.04.21								
SURVEYOR STEVE LKK 12.04.21								
POLICY NO: 1900263809-01								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	7,119.20	Nett	12,469.20
Labour	5,280.00	7% GST on	872.84
Standard Menu	0.00		
Specialist Job	180.00	Total Payable	13,342.04
Diagnostics Job	0.00		
Sundry/Others	-110.00		
Total(w/o GST)	12,469.20		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO.: **AIG**

Supplementary Parts For Registration No.: **SMR 7577 H**

	<u>Materials</u>	<u>Cost (\$)</u>
1	Clips (x10)	10.00
2	Garnish assy-Qtr side, LH	144.00
3	Retainer assy-bumper cover mtg (x10)	20.00
4	Sensor-Ambient	25.00
5	Coolant (4L)	26.00

	Total Materials	225.00
	Less 20% discount	45.00

	Total after discount	180.00

	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace rear end panel, & repair rear floor panel	800.00
2	Respray on rear end panel, & rear floor panel	700.00
3	Remove & reinstall front support panel to facilitate repair	400.00
4	Bleed hybrid motor	200.00
5	Remove & install rear seats to facilitate repair	120.00

	Total labour	2,220.00
	Total amount	2,400.00
	7% GST	168.00

	Grand total	<u>\$ 2,568.00</u>

Thank You.
Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

SNR 7577H

WIP: 31885

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Panel Assy - Back	? / SUPP	St		
2	Cover Rear Bumper Side under LH	? / SUPP	ms		
3	Bracket - RR Beam lower MTG X 2	? / SUPP	ca		Missing
4	Bracket - RR Beam lower Center MTG	? / SUPP	ca		
5	Stay - RR Bumper LH	? / SUPP	St		
6	Stay - RR Bumper RH	? / SUPP	St		
7	Bracket Assy - RR Bumper Side LH	? / SUPP	ca		
8	Ultrasonic Sensor Assy X 1	? / SUPP	ca		
9	Clip Rear Bumper X 10	? / SUPP	ae		
10	LH Rear fender wheel Arc Moulding	? / SUPP	ca		
11	Radiator Assy - Inverter	? / SUPP	St		
12	Condenser Assy	? / SUPP	St		
13	Radiator Assy	? / SUPP	St		
14	Guard Air RH	? / SUPP	ca		
15	Guard Air LH	? / SUPP	ca		
16	Guard Air Radiator	? / SUPP	ca		
17	Blower Assy	? / SUPP	ca		
18	Cover Front Bumper upr	? / SUPP	ca		
19	Cover Front Bumper lower	? / SUPP	ca		
20	Absorber - Front Bumper Energy	? / SUPP	ca		

MODEL: Viro

SURVEYOR: Steve Likh

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

WIP: 31885

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	?	SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Flap Assy - Active Air	?	SUPP	cm		
2	Duct Assy - Active Air	?	SUPP	cm		
3	Aircon Sensor	?	SUPP	cm		
4	clipp Front Bumper X10	?	SUPP	nm		
5		?	SUPP			
6	Renew Rear End panel	?	SUPP			
7	Repair rear floor panel	?	SUPP			
8	RN I rear seat for repair work	?	SUPP			
9	RN I FRT Support for repair work	?	SUPP			
10	Painting rear End panel	?	SUPP			
11	Painting rear floor panel	?	SUPP			
12	Add of day - total 16 days	?	SUPP			
13		?	SUPP			
14	Radiator Coolant	?	SUPP			
15	To bleed Hydraulic Motor	?	SUPP			
16		?	SUPP			
17		?	SUPP			
18		?	SUPP			
19		?	SUPP			
20		?	SUPP			

MODEL: N110

SURVEYOR: Steve - Lulu

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

HOME
 Online

Niro(DE HEV)/2020/G 1.6 GDI..

VCI

Fault Code Searching

Rescan

Save



27/27

System	Status	Result
ENGINE	No Current DTC	Good
MCU	No Current DTC	Good
HCULDC	No Current DTC	Good
BMS	No Current DTC	Good
AT	No Current DTC	Good
EPB	No Current DTC	Good

System	DTC	Description	State
	No Current DTC		

S/W Ver.

M-E-K-01-00-0244

VCI Ver.

02.52

ECU Ver.

M-E-K-01-00-0185

OS Ver.

Android 10