

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004640/UGA3Q2
Date: 29/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900152883
Claimant Vehicle No :	SLP1932C	Insured Vehicle No :	SKL2220A
Date of Loss:	05/04/2021	Nature of Claim:	TP
		Claim No:	0789935105SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP1932C		
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Engine No:	P520446213
Reg. Date:	29/05/2017 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0154280
Colour:	White	Odometer:	109603 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55Z R16	Rear Tyre Size:	205/55Z R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,419.20	2,402.00	6,017.20	71.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,350.00	2,320.00	63.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,089.20	3,752.00	8,337.20	68.96
Approved Total (Overridden) (S\$)		3,000.00		

Nett Amount (S\$)	12,089.20	3,000.00	9,089.20	75.18
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,407.45		

INSPECTION

Date of Assignment: 12/04/2021

Date Inspected: 13/04/2021

Estimated Period of Repair: 4.0 days

Inspected At: Profi Automotive
BLK 10 KAKI BUKIT ROAD 2
#01-05 FIRST EAST CENTRE
SINGAPORE 417868

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	1,057.00 FL	*- FL
2	1		*BOOTLID EMBLEM LOGO	Missing	78.00 FL	*74.40 FL
3	1		*BOOTLID EMBLEM -MAZDA 3	Necessary	63.00 FL	*63.00 FL
4	1		*BOOTLID EMBLEM -SKYACTIV	Necessary	38.00 FL	*38.00 FL
5	1		*BOOTLID LAMP LH	Not Necessary	566.00 FL	*- FL
6	1		*BOOTLID LAMP RH	Not Necessary	566.00 FL	*- FL
7	1		*BOOTLID LOCK	Not Necessary	277.00 FL	*- FL
8	1		*BOOTLID HINGE LH	Not Necessary	155.00 FL	*- FL
9	1		*BOOTLID HINGE RH	Not Necessary	155.00 FL	*- FL
10	1		*BOOTLID RUBBER	Not Necessary	117.00 FL	*- FL
11	1		*END PANEL	Repair	605.00 FL	*- FL
12	1		*END PANEL TOP GARNISH	Not Necessary	118.00 FL	*- FL
13	1		*END PANEL KEYLESS ANTENNA	Not Necessary	115.00 FL	*- FL
14	1		*REAR BUMPER	Deformed	1,174.00 FL	*1,074.80 FL
15	1		*REAR BUMPER REFLECTOR LH	Not Necessary	65.00 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Not Necessary	65.00 FL	*- FL
17	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	46.00 FL	*- FL
18	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	46.00 FL	*- FL
19	1		*REAR BUMPER BRACKET LH	Not Necessary	18.00 FL	*- FL
20	1		*REAR BUMPER BRACKET RH	Not Necessary	18.00 FL	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Dented	578.00 FL	*537.30 FL
22	1		*REAR EXHAUST SILENCER	Not Necessary	1,089.00 FL	*- FL
23	2		*REAR EXHAUST MOUNTING	Not Necessary	60.00 FL	*- FL
24	1		*REAR TAILLAMP LH	Not Necessary	1,015.00 FL	*- FL
25	1		*REAR TAILLAMP RH	Cracked	1,015.00 FL	*915.00 FL
26	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
28	1		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
29	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
30	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,239.00	2,942.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,819.80	540.50
Total Parts (\$\$)	8,419.20	2,402.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING	New	80.00	20.00
2	REMOVE ,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
4	REMOVE AND RENEW REAR EXHAUST	New	150.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1,200.00	500.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	700.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
			Gross Labour Cost (S\$)	3,670.00
				1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >