

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S: YUSOFF BIN AWI
BLK 846 SIMS AVENUE #04-758
SINGAPORE 400846

Estimate No: EST1506854
Date: 09 Apr 2021
Policy No: P2302547
Veh Reg No: SMM2489M
Make/Model: HYUNDAI AD AVANTE
1.6 GLS (A) S
Chassis No: KMHD841CMKU917287
Engine No: G4FGKU154189
Reg. Date: 24/06/2019

ATTN: CHINA TAIPING

Your Ref No: TP 0421-6318
Claim Type: Third Party
Accident Date: 05/04/2021
TP Veh Reg No: SGX 8929 J

Vecon

Estimate Repair Cost to Vehicle No :SMM2489M

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BUMPER <i>Distorted</i>	459.40	1 PC	459.40 ✓	
2 REAR BUMPER CLIPS <i>new</i>	4.90	10 PC	49.00 ✓	
3 REAR BUMPER SIDE HOLDER - LH <i>new</i>	44.30	1 PC	44.30 +	
4 REAR BUMPER SIDE HOLDER - RH <i>new</i>	44.30	1 PC	44.30 +	
5 REAR BUMPER FOAM <i>new</i>	0.00	1 PC	0.00 +	
6 REAR BUMPER BRACKET - LH & RH <i>new</i>	10.10	2 PC	20.20 +	
7 REAR BUMPER REINFORCEMENT <i>new</i>	294.80	1 PC	294.80 +	
8 REAR BUMPER REINFORCEMENT LOWER BRACKET <i>new</i>	67.80	1 PC	67.80 +	
9 REAR BUMPER LOWER <i>cracked</i>	353.50	1 PC	353.50 ✓	
10 REAR BUMPER LOWER REFLECTOR - RH <i>cut</i>	201.50	1 PC	201.50 ✓	
11 REAR BUMPER SENSOR <i>new</i>	137.50	2 PC	275.00 +	
12 TAIL LAMP - RH <i>new</i>	876.80	1 PC	876.80 +	
13 TAIL LAMP CLIP - RH	6.90	1 PC	6.90 +	
14 REAR PANEL <i>new</i>	454.60	1 PC	454.60 +	
15 REAR PANEL TOP GARNISH <i>new</i>	78.20	1 PC	78.20 +	
			3,226.30	
		Less 20%	645.26	2,581.04
Special Net				
16 REAR NUMBER PLATE WITH CASING <i>new</i>	45.00	1 SET	45.00 +	
17 REAR BUMPER SENSOR <i>Repeated.</i>	220.00	1 SET	220.00 +	
			265.00	265.00
Labour				
18 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	600.00	1 JOB	600.00 → 400	
19 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.00	1 JOB	800.00 → 400	
20 TO CHECK WIRING	50.00	1 JOB	50.00 30	
21 TO TUFF-KOTE	60.00	1 JOB	60.00 +	
22 TO REMOVE, REFIX REAR GARNISH, CUSHION, CARPET AND RELATED PARTS	80.00	1 JOB	80.00 40	
23 TO TRANSFER REAR BUMPER SENSOR	50.00	1 JOB	50.00 ✓	
			1,640.00	1,640.00

1063.40

850.72

920

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : YUSOFF BIN AWI
BLK 846 SIMS AVENUE #04-758
SINGAPORE 400846

ATTN: CHINA TAIPING

Your Ref No: TP 0421-6318
Claim Type: Third Party
Accident Date: 05/04/2021
TP Veh Reg No: SGX 8929 J

Estimate No: EST1506854
Date: 09 Apr 2021
Policy No: P2302547
Veh Reg No: SMM2489M
Make/Model: HYUNDAI AD AVANTE
1.6 GLS (A) S
Chassis No: KMHD841CMKU917287
Engine No: G4FGKU154189
Reg. Date: 24/06/2019

Estimate Repair Cost to Vehicle No :SMM2489M

Description	U/Price	Quantity	Price SS	Amount SS
Total				S\$ 4,486.04
Add GST @ 7%				314.02
Total Amount Payable				S\$ 4,800.06

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED AND CENTS SIX ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Admin Ling.
T/P 29/04/21.

No of Days: ~~4 Days~~ 4 Days.

total: 1770.72
(P/P)