



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL Ref: CS/SMO21004642/Utf3
 50 RAFFLES PLACE #03-03 Date: 13/04/2021
 SINGAPORE LAND TOWERS SINGAPORE 048623 Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBR 3958Z	Veh. Inspected	SMR 1944X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2101124/THE	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	13/04/2021

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/04/2021	Inspection Date	13/04/2021
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.