

AERO GARAGE PTE LTD
BLK 160 SIN MNG DRIVE

#08-07

SINGAPORE 575722

Vehicle Number : **SMX 1570J**
 Vehicle Model : **HONDA VEZEL**
 Accident Date : **10.04.2021**

Date : **02.09.2021**
 Chassis : **RU31207110**

Not Authen
106 11 Sep & 12, 804
12 day

ESTIMATE

1	1 pc	Tailgate	953		1,140.00	✓
2	1 pc	Tailgate Windscreen Moulding			198.00	✓
3	1 pc	Tailgate Windscreen Inner Seal			60.00	3052
4	1 pc	Tailgate Badge			65.50	✓
5	1 pc	Tailgate VEZEL Emblem			89.80	✓
6	1 pc	Tailgate HYBRID Emblem			94.50	✓
7	1 pc	Tailgate Outer Garnish			49.50	X
8	2 pcs	Tailgate Number Plate Lamps		78.00	156.00	X
9	1 pc	Tailgate Opener Switch			214.50	X
10	1 pc	Tailgate Lamps			398.70	✓
11	1 pc	Tailgate Stopper			3.00	✓
12	1 pc	Tailgate Inner Trim	368.20		476.70	✓
13	1 pc	Tailgate Inner Side Trim			268.20	X
14	1 pc	Tailgate Inner Top Trim			298.90	X
15	1 pc	Tailgate Pocket Handle			98.90	X
16	1 pc	Tailgate Inner Lock			678.00	✓
17	1 pc	Tailgate Lock Catch			79.00	X
18	1 pc	Tailgate Weatherstrip	138.45	Dis 1/2	276.90	✓ 5052
19	1 pc	Tailgate Auto Lock Actuator			319.20	X
20	2 pcs	Tailgate Hinges		114.00	228.00	X
21	2 pcs	Tailgate Absorbers	0192.50		535.80	✓
22	2 pcs	Taillamps			568.80	✓ 284.40
23	2 pcs	Taillamps Inner Sealer			35.00	✓
24	1 pc	Taillamps Inner Panel RH			168.00	✓
25	1 pc	Rear Bumper	762.70		698.20	✓
26	2 pcs	Rear Bumper Side Retainers	078.40	0/1 cm	197.80	✓
27	2 pcs	Rear Bumper Attachment Retainers		0/1 cm	264.40	✓
28	2 pcs	Rear Bumper Refelctors Lamps	0110	0/1 cm	355.80	✓
29	2 pcs	Rear Bumper Side Pad	0195	0/1 cm	469.80	✓
30	1 pc	Rear Bumper Under Cover	250	Dis 1/2	349.90	✓

C/F

8,836.80

AERO GARAGE PTE LTD
BLK 160 SIN MNG DRIVE
#08-07
SINGAPORE 575722

				B/F	8,836.80	
31	1 pc	Rear Air Vents	120.70		R 278.90	✓
32	1 pc	End Panel	415.60		B 512.80	✓
33	1 pc	End Panel Top Trim	188		D 258.90	✓
34	1 pc	Rear Floor Panel			R 898.00	X
35	1 pc	Rear Floor Panel Top Board			Return 356.70	✓
36	1 pc	Rear Floor Panel Top Tool Sponge			CM 413.20	✓
37	1 pc	Spare Tyre Under Dust Cover			CM 368.70	✓
38	1 pc	Rear Chassis Frame Member RH			R 523.40	X
39	1 pc	Rear Fender RH	988.50		B 1,096.00	✓
40	1 pc	Rear Fender Inner Trim RH	365.80		Return 499.20	✓
41	1 pc	Rear Fender Inner Top Trim RH			in 345.60	X
42	1 pc	Rear Fender Quarter Garnish RH			in 128.00	X
43	1 pc	Rear Fender Arch Garnish RH	199.10		B 268.90	✓
44	2 pcs	Rear Fender Inner Shield			disc 199.60	✓ + 99.80
45	1 pc	Rear Exhaust Silencer	785.20		B 900.00	✓
46	2 pcs	Rear Exhaust Mountings	033	46.00	D 92.00	✓
47	1 pc	Rear Exhaust Gasket			M 48.00	✓
48	1 pc	Center Exhaust Pipe			B 950.00	✓
49	2 pcs	Center Exhaust Mountings		46.00	in 92.00	X
50	1 pc	Center Exhaust Gasket			M 48.00	✓
51	1 pc	Rear Key Antenna Sensor			in 197.80	X
52	1 pc	Alarm Sensor Speaker			in 234.20	X
53	1 pc	Rear Retactable Board			in 427.70	X
54	1 pc	Rear Shock Absorber RH	292.30		R 425.00	✓
55	1 pc	Rear Wheel Bearing RH			M 353.50	✓
56	1 pc	Rear Lower Arm RH			N/P 456.40	X
57	1 pc	Rear Knuckle Arm RH			N/P 345.80	X
58	1 pc	Rear Axle Beam	1490.70		B 2,902.80	✓
					22,457.90	
					Less 20%	4,491.58
						17,966.32
					C/F	17,966.32

AERO GARAGE PTE LTD
BLK 160 SIN MNG DRIVE
#08-07
SINGAPORE 575722

B/F

17,966.32

Special Nett

1	1 pc	Tailgate Windscreen Sealant		na 60.00	SN 405a
2	1 set	Tailgate Lamp Clips		na 50.00	SN X
3	1 set	Tailgate Inner Trim Clips		na 60.00	SN ✓
4	1 pc	Tailgate Outer Garnish Clips		na 50.00	SN X
5	1 pc	Rear Number Plate with Cover		fu 120.00	SN X
6	1 set	Rear Bumper Clips		na 60.00	SN ✓
7	1 set	Rear Bumper Under Cover Clips		na 60.00	SN ✓
8	1 set	End Panel Top Trim Clips		na 60.00	SN ✓
9	1 set	Taillamps Clips		el/na 50.00	SN 205a
10	1 set	Rear Fender Inner Trim Clips		na 60.00	SN ✓
11	1 set	Rear Fender Inner Side Trim Clips		na 60.00	SN X
12	1 set	Rear Fender Inner Top Trim Clips		na 60.00	SN X
13	1 set	Rear Fender Arch Garnish Clips		na 60.00	SN ✓
14	1 set	Rear Fender Inner Shield Clips		na 60.00	SN X
15	1 set	Reverse Sensor		na/shay 280.00	SN 2005a
16	1 pc	Rear Sport Rim RH		fu 450.00	SN X
17	1 pc	Rear Tyre RH		fu 350.00	SN X
18	1 set	Body Panel Joint Sealant		na 120.00	SN 605a
19	1 pc	Rear Floor Panel Insulator Pad		na 150.00	SN X
20	1 pc	Rear Floor Panel Top Insulator Tray		na 450.00	SN X

2,670.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

C/F

20,636.32

AERO GARAGE PTE LTD
BLK 160 SIN MNG DRIVE

#08-07

SINGAPORE 575722

B/F

20,636.32

Labour charge

Panel Beating		2,000.00	1600
Spray painting		1,800.00	1400
Check Wiring		100.00	20
Anti rust		180.00	90
Towing fees. (King Dolly)		150.00	120
Remove and install rear windscreen.		140.00	120
Remove and install tailgate parts.		90.00	60
Remove and install carpet and seat.		150.00	120
Remove and install reverse sensor		90.00	50
Remove and install rear undercarriage.		650.00	220
To perform computerize wheel alignment		90.00	60
To jack and alignment chassis frame member.		380.00	250
		\$ 26,456.32	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey, is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: