



BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE #01-49, PREMIER @ KAKI BUKIT,
SINGAPORE 415875

Estimate for SLV3187S (Hyundai Elantra)

Qty	Spare Parts	List Price (\$)	
1	Bonnet	\$ 1240.70	NDX
1	Front bumper	\$ ✓ 474.40	BRX
1	Front bumper centre rubber seal	\$ 28.40	NSX
1	Front bumper number plate garnish	\$ 74.10	NDX
1	Front bumper RH side retainer	\$ ✓ 28.00	} NSX ✓
1	Front bumper LH side retainer	\$ ✓ 28.00	
1	Front bumper inner sponge	\$ 100.70	NDX BRV
1	Front bumper upper reinforcement	\$ 695.80	} NSX
1	Front bumper lower reinforcement	\$ 85.10	
1	Front bumper RH fog lamp cover	\$ 115.40	} NDX
1	Front bumper RH fog lamp	\$ 265.10	
1	Front bumper LH fog lamp cover	\$ 115.40	
1	Front bumper LH fog lamp	\$ 265.10	
1	Front black grille RH sensor	\$ 202.20	} NSX
1	Front black grille LH sensor	\$ 202.20	
1	Support panel	\$ 949.30	} NSX
1	Aircon condenser	\$ 745.10	
1	RH headlamp	\$ ✓ 1,198.80	BRV ✓
1	RH headlamp support bracket	\$ 24.00	NSX
1	LH headlamp	\$ ✓ 1,198.80	BRV ✓
1	LH headlamp support bracket	\$ 24.00	NSX
1	Rear bumper	\$ 489.40 520.40	BRV ✓
1	Rear bumper RH side retainer	\$ ✓ 44.30	NECV ✓
1	Rear bumper RH splash shield	\$ ✓ 42.10	BRV ✓
1	Rear windscreen glass rubber seal	\$ ✓ 79.20	NECV ✓
1	RH rear fender	\$ ✓ 1,768.30	DDV ✓
1	RH rear fender transparent sticker	\$ 24.80	NSX
1	RH taillamp	\$ ✓ 362.60	BRV ✓
1	RH rear knuckle arm	\$ ✓ 387.05	BTV ✓
1	RH rear wheel bearing	\$ 302.00 452.00	JMV ✓
1	RH rear shock absorber	\$ ✓ 341.90	} BTV
1	RH rear lower arm	\$ 387.00 401.00	
1	RH rear upper arm	\$ ✓ 162.30	
1	RH rear trailing arm	\$ 209.00 278.40	

\$ 11,684.25
 -20% \$ 2,336.85

 \$ 7503.15
 @ 20% 1500.63
 6000.52

\$ 9,347.40

Qty Spare parts

- 1 Front bumper clips (set)
- 1 Front number plate
- 1 Front bumper lower spoiler
- 1 Front black grille
- 1 Front black grille clips (set)
- 1 Rear bumper clips (set)
- 1 Rear windscreen glass sealant
- 1 Rear windscreen glass inner seal
- 1 RH rear sport rim
- 1 RH rear tyre

Special Nett (\$)

\$ 30.00	70.00	NECV ✓
\$	70.00	NDX
\$	900.00	NDX
\$	750.00	cut ✓
\$	60.00	NSX
\$ 30.00	70.00	NECV ✓
\$ 40.00	70.00	NECV ✓
\$	50.00	RPTX
\$	800.00	NDX
\$ 200.00	350.00	punctured ✓

1950.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels (front portion)

\$ 200.00 ~~800.00~~ ✓

Spray painting on affected panels (front portion)

\$ 250.00 ~~700.00~~ ✓

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels (rear portion)

\$ 600.00 ~~1,000.00~~ ✓

Spray painting on affected panels (rear portion)

\$ 600.00 ~~1,000.00~~ ✓

Check wiring and lighting system (front and rear)

\$ 30.00 ~~100.00~~ ✓

Apply rust coating on affected areas

\$ 30.00 ~~80.00~~ ✓

Remove and replace aircon condenser and pipes to facilitate repairs. To refill
aircon gas

\$ ~~180.00~~

Remove and reinstall radiator, hoses and fan assy to facilitate repairs. To refill
radiator coolant

\$ 180.00

Remove and reinstall rear windscreen glass to facilitate repairs

\$ 170.00 ~~180.00~~ ✓

Remove and reinstall rear inner trims, garnish, roof lining and seats to facilitate
repairs

\$ 250.00 ~~X~~ NN

Remove and reinstall rear bumper reverse sensors to facilitate repairs

\$ 40.00 ✓

Conduct, test drive and adjust wheel alignment system

\$ 60.00 ~~100.00~~ ✓

Remove and replace rear undercarriage parts to facilitate repairs

\$ ~~120.00~~ ~~220.00~~
1420.00

Total: \$ 17,367.40

Survey
13/4/2021
1245 hrs
TALIM MUR

Resurvey
16/4/2021
1155 hrs
TALIM MUR

PARTS 6002.52
SN 1050.60
LABOUR 1420.00

8472.52
@ 20% 1694.50

6778.02

Lump sum repair
Repair days 7

L/S 6750/2

TALIM MUR
27/4/2021

Insurers hence notify
insurers of the following:
• Resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: