

Claim Audit

AUDIT TRAIL			
No.	On	Audit	Remarks
1	19 Mar 2021 00:31	Clm Veh Model Changed	
2	19 Mar 2021 00:31	Clm Created	Reg No: SMF2133B. Policy No: 1800129371-02. Acct Date: 2021/03/18. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R213I0002
3	24 Mar 2021 16:10	Clm Registration Modified	Acct Time:11:45:00->11:00:00. Pol No:1800129371-02->1800129371.
4	13 Apr 2021 14:20	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.
5	13 Apr 2021 14:20	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)
6	13 Apr 2021 14:20	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):
7	13 Apr 2021 14:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/04/22
8	13 Apr 2021 14:20	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.
9	13 Apr 2021 14:20	Clm Registration Modified	Rep:1137->200611.
10	13 Apr 2021 14:20	Clm Veh Model Changed	(205844) AUDI A3 1.4 TFSI S-TRONIC (A).
11	13 Apr 2021 14:21	Adj Adjuster Assigned	[None] -> ADRIAN LING
12	14 Apr 2021 12:43	Clm Registration Modified	Init.Est.:->5,000 - 6,000. 2F Remarks: -> Not Applicable. GST: -> 7.00.
13	14 Apr 2021 16:34	Adj Rpt Initiated	
14	14 Apr 2021 16:34	Insured Phone No Updated	[6596859598] -> [+656596859598]
15	14 Apr 2021 16:34	Clm Dtl Modified	Claim Conclusion: -> 3.
16	14 Apr 2021 16:34	Clm Dtl Modified	JPJ Reg. Date: -> 2018/10/30.
17	14 Apr 2021 16:34	Clm Details Notified	
18	14 Apr 2021 17:56	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/04/22
19	14 Apr 2021 17:56	Adj Mandate Request	Cur.Req:7085.00:DAMGE CONSISTENT REPAIR COST ECONOMICAL
20	16 Apr 2021 14:33	Clm Registration Modified	Excess: -> 600.00.
21	16 Apr 2021 14:33	Label Added	(20226):Coverage Confirmed.
22	16 Apr 2021 15:28	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/04/22. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repa
			By
			[] Merimen Administrator
			[I] Merimen Administrator
			[I] Low, Xianyu
			[] CELINE FONG
			[] CELINE FONG
			[A] CELINE FONG
			[A] CELINE FONG
			[A] CELINE FONG
			[A] CELINE FONG
			[A] CELINE FONG
			[A] CELINE FONG
			[I] Mithoo Singh, Aashweenjeet Kaur
			[A] HUEY YON
			[A] HUEY YON
			[A] HUEY YON
			[A] HUEY YON
			[A] HUEY YON
			[A] DENISE TAY KWEE CHENG
			[A] DENISE TAY KWEE CHENG
			[I] Mithoo Singh, Aashweenjeet Kaur
			[A] Merimen Administrator
			[I] Lim, Kok-Chong

AUDIT TRAIL				
No.	On	Audit	Remarks	By
23	16 Apr 2021 15:28	Adj Mandate Set	Approved:6566.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From

Date To

Audit Type

None

Go

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2686251	14 Apr 2021 16:34:08	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMF2133B		11.00