

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0304/2021/HR  
**DATE** : 9-Apr-21  
**WIP** : 22672

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/4/21**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR. THAM CHING HIONG  
**ADDRESS** : 3Q LIMAU GARDEN  
SINGAPORE 466050  
**TELEPHONE** : HP +65 97922858  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1900247537  
**VEHICLE NO** : **SMQ 5039 M**  
**MODEL CODE** : Q3 1.4 TFSI S TRONIC  
**MODEL YEAR** : 21/11/2019  
**ENGINE NO** : CZD 884429  
**CHASSIS NO** : WAUZZZF39L1021914  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 8-Apr-21  
**PLACE OF ACCIDENT** : NEAR 321 ORCHARD ROAD.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 5039 M**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	X.
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	✓
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500.
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	\$ 3,000.00	550.
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 6,352.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5039 M**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH <i>Regr</i>	1	\$ 2,909.00	<i>X</i>
2	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 135.00	<i>X</i>
3	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 311.00	<i>X</i>
4	REAR DOOR CATCH <i>new</i>	1	\$ 120.00	<i>X</i>
5	REAR DOOR ARCH COVER - LH <i>cut</i>	1	\$ 257.00	<i>✓</i>
6	REAR WHEEL ARCH COVER - LH / RH <i>LH cut</i>	1	\$ 536.00	<i>262 .</i>
7	REAR BUMPER UPPER GUIDE SECTION - LH <i>new</i>	1	\$ 63.00	<i>X</i>
8	<i>Rear wheel Rim</i> <i>not Nec</i>	1	\$ 1,566.00	<i>X</i>
9	SUNDRIES		\$ 200.00	<i>?</i>
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 6,097.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 6,352.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 12,449.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

: *Adrian Ling*  
: *13/04/21*  
:  
:  
:  
: *are Authorised, 03 Days*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT