

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0304/2021/HR
DATE : 9-Apr-21
WIP : 22672

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. THAM CHING HIONG
ADDRESS : 3Q LIMAU GARDEN
SINGAPORE 466050
TELEPHONE : HP +65 97922858
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900247537
VEHICLE NO : **SMQ 5039 M**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 21/11/2019
ENGINE NO : CZD 884429
CHASSIS NO : WAUZZZF39L1021914
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Apr-21
PLACE OF ACCIDENT : NEAR 321 ORCHARD ROAD.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 5039 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	X.
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	✓ ✓
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500. ✓
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	\$ 3,000.00	550. 1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 6,352.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5039 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH <i>Regis</i>	1	\$ 2,909.00	+
2	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 135.00	+
3	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 311.00	+
4	REAR DOOR CATCH <i>new</i>	1	\$ 120.00	+
5	REAR DOOR ARCH COVER - LH <i>cut</i>	1	\$ 257.00	✓ 205.20
6	REAR WHEEL ARCH COVER - LH / RH <i>LH cut</i>	1	\$ 536.00	262 214.40
7	REAR BUMPER UPPER GUIDE SECTION - LH <i>new</i>	1	\$ 63.00	+
8	Rear wheel Rim <i>not nec</i>	1	\$ 1,566.00	+
9	SUNDRIES <i>not nec</i>		\$ 200.00	?
TOTAL SPARE PARTS		:	\$ 6,097.00	
TOTAL LABOUR CHARGES		:	\$ 6,352.00	
GRAND TOTAL		:	\$ 12,449.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *13/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *are Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Veron

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0304/2021/HR
7-May-21
CHANG
1 of 1
SMQ 5039 M
AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR.	S/N \$ 280.00	✓ ✓
2	TO RESPRAY LHS FRONT DOOR.	\$ 1,000.00	550. ✓
Parts			
1	FRONT DOOR COVER - LH <i>ut</i>	\$ 268.00	214.40
2	WHEEL ARCH TRIM GROMMET <i>Nec</i>	\$ 26.00	20.80
GRAND TOTAL		\$ 1,574.00	

For Premium Automobiles Pte Ltd

Adrian Ling
07/05/21.
[Signature]



Authorised Signature