



YE KOK WEE
LK 436A FERNVALE ROAD #12-188
SINGAPORE 791436

Attention : THE OWNER
Contact : 91002933

Not Authorised
11/11/21 8:110d
Recovery After Pain
3 days

Estimate : ES007168

Date : 13/04/2021
Vehicle Num. : SLE5422P
Make/Model : MAZDA 5-2016
Chassis/Eng# : JM6CW1071G0123979/PE10351811
Accident Date : 09/04/2021
Claim No. :
Reference :
Policy No. :

Quantity	Particular	Unit Price	Amount S\$
----------	------------	------------	------------

LIST ITEMS :

1	FRONT BUMPER	
1	FRONT BUMPER BRACKET L/H	
8	FRONT BUMPER CLIP	
1	FRONT BUMPER SIDE RETAINER L/H	
1	FRONT FENDER L/H	
1	FRONT FENDER INNER SHEILD L/H	
1	FRONT SHOCK ABSORBER L/H	220.60
1	FRONT WHEEL BEARING L/H	
1	FRONT LOWER ARM L/H	311.60

List Total S\$:
15.00% Discount S\$:

1	1,156.00	X
1	70.20	X
8	60.80	X
1	132.00	X
1	599.70	X
1	201.40	X
1	265.90	X
1	286.00	X
1	411.80	X
	3,183.80	
	477.57	
	2,706.23	

LABOUR :

COMPUTER WHEEL ALIGNMENT
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
REMOVE & REINSTALL FRONT SUSPENSION L/H
TO KNOCK & STRAIGHTEN L/H FRONT CHASSIS FRAME AND ALL
NECESSARY PARTS

Labour Total S\$:

1	120.00	X
1	100.00	X
1	900.00	X
1	250.00	X
1	1,100.00	X
	2,470.00	

ars : Five Thousand One Hundred Seventy-Six & Cents Twenty-Three Only

Total S\$: 5,176.23
=====

ETE VMS PTE LTD

an estimate bases on our preliminary inspection and does not cover additional parts and labour time which
quired after the work has begun

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to time which
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer