

SMK 408X.

TP Budget Direct.
Veron.

Toyota Vios 1496cc

MR2B23F3X01171301

Rees Bumper Deband	440.10. ✓
Rees Bumper Clips. ^{new}	30(SN) ✓
Rees Bumper Side Holder x 02	^{new} 65.10 130.20 ✓ 66.4 x 2 = 123.20
Rees Bumper Reflector LH. ^{cracked}	120.40 ✓
Rees Bumper Reinforcement. ^{Dented}	3 x 3.80 ✓
Rees Bumper Reinforcement Bracket x 02.	^{new} 114.8 x 2 = 229.60 X
Reverse Sensor x 02 Dmg'd	^{200(SN)} 280(SN) ✓
Rees End Panel. ^{Dented}	768 ✓
Rees End Panel Top Garnish.	^{new} 205.60 X
Rees End Panel Top Garnish Clips.	^{new} 90(SN) X
Rees End Panel Sealant. ^{New}	60(SN) ✓
Taillamp LH. ^{Cracked}	422.50. ✓

SMK 408X.

Toyota Logo.	} Not New	50.20	x
Vios Emblem.		43.60	x
E Emblem.		45.50	x

Panel Beating. ~~800~~ 600

Spray Painting. ~~800~~ 500

Wiring. ~~50~~ 30

To remove reverse sensor ~~100~~ 50

To remove upholstery. ~~150~~ 50

To spray tuff coat ~~150~~ 60

5239.90

list: 2218

Labour: 1290

less 25%: 1663.50. Total: 3243.50

S.N: 290

H/S: 26K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: