



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21004663/R1uf3e2	
			Date: 24/05/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 591E	Veh. Inspected	YN 367Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/03/21/2090	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	13/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi FE83BE6SRDEA	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	FE83BEA20072	Colour	WHITE	
Odometer	258148 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16LT	AUSTONE	7 mm	
L/H Front Tyre	7.00 R16LT	AUSTONE	7 mm	
R/H Rear Tyre	7.00 R16LT (D)	AUSTONE	7/7 mm	
L/H Rear Tyre	7.00 R16LT (D)	AUSTONE	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/03/2021	Inspection Date	13/04/2021	
Survey held at	No. 8 Tuas Avenue 18, Singapore 638892.			
Repairer	VENDA ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	