

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0317/2021/HR
DATE : 14-Apr-21
WIP : 23067

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/4/21

YOUR INSURED VEH NO : SMC 8028 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR.TEO KOON SOON
ADDRESS : BLK 7 FERNVALE CLOSE
#06-16
SINGAPORE 797488
TELEPHONE : HP +65 94569900
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800044849-01
VEHICLE NO : **SKN 8892 K**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 26/4/2018
ENGINE NO : CVK056499
CHASSIS NO : WAUZZZF45JA124687
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Apr-21
PLACE OF ACCIDENT : NEAR KPE PAYA LEBAR AIR BASE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 8892 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	
3	TO RESPRAY REAR BUMPER.	\$	900.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		: \$	2,502.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 8892 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,181.00	
2	REAR BUMPER FIXING PARTS	1		
3	REAR BUMPER SECURING STRIP	1	\$ 223.00	
4	REAR BUMPER SPOILER	1	\$ 249.00	
5	REAR LIGHT REFLECTOR - LH / RH	1	\$ 82.00	
6	REAR BUMPER CARRIER	1	\$ 940.00	
7	REAR BUMPER SEAL	2	\$ 28.00	
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 46.00	
9	REAR BUMPER PARKING AID SENSOR - INNER / OUTER	2	\$ 488.00	
10	REAR BUMPER PARKING AID SENSOR SEAL RING	4	\$ 9.00	
11	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS		:	\$ 4,446.00	
TOTAL LABOUR CHARGES		:	\$ 2,502.00	
GRAND TOTAL		:	\$ 6,948.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT