

TPAXA. SLC 7824 K. 2016 May.
Ceilia. Mitsubishi Outlander.
JmYXTG F3W6Z003857.

Rear Bumper.	Distorted	988	✓
Rear Bumper Clips.	✓	30(SN)	✓
Rear Bumper Side Holder RH	2nd	62	✓
Rear Bumper Lower Garnish	Rel	342	✓
Rear Bumper Reflector RH.	Missing	142	✓
Rear Bumper Impact Bracket RH	MP	148	+
Rear Bumper Side Protector RH.	Cut	95	✓
Rear End Panel.	Dented	689	✓
Rear End Panel Sealant.	✓	60(SN)	✓
Rear End Panel Top Garnish.	MP	191	+
Rear End Panel Top Garnish Clips.	MP	20(SN)	+
Tailgate.	Dented	1039	✓
Tailgate Glass Moulding.	2	182	✓
Tailgate Glass Sealant.	✓	60(SN)	✓
Outlander Bording.	2	85	✓
Cycle and Carriage Emblem.	✓	45	✓
Taillamp RH.	cracked	651	✓
Reverse Sensor	MP	280(SN)	+

SLC 7824K.

Reer RH Fender	2yr	1125	x
Reer RH Fender Inner Shield	cut	89	-
Reer RH Fender Inner Shield clips.	~	20(SN)	-
Reer RH Fender Glass Sealant.	~	40(SN)	x
Reer Exhaust Pipe.	Dented	688	✓
Reer Exhaust Mounting.	~	45	x
Reer Exhaust Gasket.	~	28	✓

Panel Beating.	1400	1000
Spray Painting.	1400	900
Wiring.	50	30
To spray tuft coat	150	60
To remove reuse sensor	100	50
To remove rear camera.	100	50
To remove upholstery.	150	80
To remove rear fender glass	120	x
To remove tailgate glass	180	120
To transfer tailgate fittings.	150	80
To remove exhaust pipe.	150	80

hist: 5125

len 10% : 4612.50

S.N. 170

Labour: 2450

total: 7232.50

L/S: 5.81k.

07 days

5800

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: