



AIG - OD CLAIM
SURVEY: 13/04/21
LKK - STEVE

VEHICLE NO : SLP 5231R

MODEL : HA/NIRO 1.6 A

WIP : 31881

Material	:	\$	<u>8,707.20</u>
Labour	:	\$	<u>3,010.00</u>
Sub-Total	:	\$	<u>11,717.20</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>1,000.00</u>
Total	:	\$	<u>10,717.20</u>
GST 7%	:	\$	<u>750.20</u>
Grand Total	:	\$	<u>11,467.40</u>
Finalise By/Date : <u>Larry on 05/05/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 09 WORKING DAYS + 4 days (2 wk. ends)

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13404/MR HAAWAYZ Reg No/Reg Date SLP5231R / 08/06/2017 Date In/Mileage 20/04/2021/ 81350 Chassis/Package KNACC81CVH506245E /# Engine No G4LEHS186824 Make/Model KIA/NIRO 1.6 A Colour/Trim ABP AURORA BLACK / WK SATURN BLACK
14/04/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	05/05/2021/ 12:25	BLE	884 / Lauro Songcuan	31881		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							800.00
RENEW FRONT BUMPER & BONNET, REPAIR LH FRONT FENDER							
E PNT98000							1050.00
SPRAY PAINT FRONT BUMPER , BONNET & LH FRONT FENDER							
E PNT88000							100.00
RENEW AIRCON CONDENSER & RADIATOR ASSY							
A 54900099							30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							80.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
M SUNDRY							40.00
SUPPLY BODY PANEL SEALANT							
M SUNDRY							20.00
SUNDRIES							
A 54900099							120.00
DISCONNET MAIN BATTERY CABLE TO FACILITATE REPAIR							
A 10028901							120.00
BLEED ON ENGINE COOLANT SYSTEM AFTER REPAIR → Supp.							
S SPECIALISTJOB							80.00
VACUUM & TOP UP AIRCON GAS (NIRO)							
S SPECIALISTJOB							50.00
SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)							
E PNT88000							400.00
REPLACE FRONT SUPPORT PANEL → Supp.							
X EXC							-1000.00
EXCESS							
X COVER-FR BUMPER UPR ✓				1.00	632.00	20.00	505.60
X COVER ASSY-FR BUMPER LWR ✓				1.00	346.00	20.00	276.80
X LOGO ASSY-KIA SUB ✓				1.00	51.00	20.00	40.80
X CAP-FRONT HOOK ✓				1.00	7.00	20.00	5.60

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 14/04/2021	<table> <tr> <td>Cust No/Name</td><td>LCV13404/MR HAAWAYZ</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLP5231R / 08/06/2017</td></tr> <tr> <td>Date In/Mileage</td><td>20/04/2021/ 81350</td></tr> <tr> <td>Chassis/Package</td><td>KNACC81CVH506245E /#</td></tr> <tr> <td>Engine No</td><td>G4LEHS186824</td></tr> <tr> <td>Make/Model</td><td>KIA/NIRO 1.6 A</td></tr> <tr> <td>Colour/Trim</td><td>ABP AURORA BLACK / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV13404/MR HAAWAYZ	Reg No/Reg Date	SLP5231R / 08/06/2017	Date In/Mileage	20/04/2021/ 81350	Chassis/Package	KNACC81CVH506245E /#	Engine No	G4LEHS186824	Make/Model	KIA/NIRO 1.6 A	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK
Cust No/Name	LCV13404/MR HAAWAYZ														
Reg No/Reg Date	SLP5231R / 08/06/2017														
Date In/Mileage	20/04/2021/ 81350														
Chassis/Package	KNACC81CVH506245E /#														
Engine No	G4LEHS186824														
Make/Model	KIA/NIRO 1.6 A														
Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/05/2021/ 12:25	BLE	884 / Lauro Songcuan	31881
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X PIECE-FRT BUMPER GUARD LWR,LH ✓		1.00	16.00	20.00	12.80 ✓
X PIECE-FRT BUMPER GUARD LWR,RH ✓		1.00	16.00	20.00	12.80 ✓
X COVER ASSY-RADIATOR GRILLE UPR ?		1.00	40.00	20.00	32.00 ?
X GRILLE ASSY-RADIATOR ✓		1.00	441.00	20.00	352.80 ✓
X ABSORBER-FRONT BUMPER ENERGY ?		1.00	68.00	20.00	54.40 ?
X GRILLE-FRONT BUMPER ✓		1.00	232.00	20.00	185.60 ✓
X LAMP ASSY-FRONT FOG & DRL,LH ?		1.00	638.00	20.00	510.40 ?
X LAMP ASSY-FRONT FOG & DRL,RH ?		1.00	638.00	20.00	510.40 ?
X FLAP ASSY-ACTIVE AIR,LWR ✓		1.00	328.00	20.00	262.40 ✓
X BRACKET-FR BUMPER SIDE,LH ?		1.00	12.00	20.00	9.60 ?
X BRACKET-FR BUMPER SIDE,RH ?		1.00	12.00	20.00	9.60 ?
X PANEL ASSY-HOOD ✓		1.00	1222.00	20.00	977.60 ✓
X HINGE ASSY-HOOD,LH x ?		1.00	40.00	20.00	32.00 ?
X HINGE ASSY-HOOD,RH x ?		1.00	40.00	20.00	32.00 ?
X CLIP-HOOD INSULATING PAD MTG ✓		12.00	1.00	20.00	9.60 ✓
X LATCH ASSY-HOOD ?		1.00	123.00	20.00	98.40 ?
X CARRIER ASSY-FRONT END MODULE ?		1.00	675.00	20.00	540.00 ?
X BEAM COMPLETE-FR BUMPER ✓		1.00	551.00	20.00	440.80 ✓
X LAMP ASSY-HEAD,LH ?		1.00	904.00	20.00	723.20 ?
X LAMP ASSY-HEAD,RH ?		1.00	904.00	20.00	723.20 ?
X SPEAKER ASSY-VESS ?		1.00	149.00	20.00	119.20 ?
X CONDENSER ASSY-COOLER ✓		1.00	639.00	20.00	511.20 ✓
X RADIATOR ASSY-INVERTER ?		1.00	768.00	20.00	614.40 ?
X RADIATOR ASSY ?		1.00	492.00	20.00	393.60 ?
X GUARD-AIR,LH ?		1.00	29.00	20.00	23.20 ?
X GUARD-AIR,RH ?		1.00	29.00	20.00	23.20 ?
X BLOWER ASSY ?		1.00	546.00	20.00	436.80 ?
X CLIP-HOOD STAY ROD		1.00	2.00	20.00	1.60 x
X COOLANT (4L)		1.00	26.00	20.00	20.80 x
X RETAINER ASSY-BUMPER COVER MTG		10.00	2.00	20.00	16.00 x
X DUCT ASSY-ACTIVE AIR		1.00	78.00	20.00	62.40 x
X HORN ASSY-LOW PITCH		1.00	79.00	20.00	63.20 x
X HORN ASSY-HIGH PITCH		1.00	79.00	20.00	63.20 x

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13404/MR HAAWAYZ Reg No/Reg Date SLP5231R / 08/06/2017 Date In/Mileage 20/04/2021/ 81350 Chassis/Package KNACC81CVH506245E /# Engine No G4LEHS186824 Make/Model KIA/NIRO 1.6 A Colour/Trim ABP AURORA BLACK / WK SATURN BLACK
14/04/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/05/2021/ 12:25	BLE	884 / Lauro Songcuan	31881

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT OD CLAIM - AIG SURVEY: STEVE (LKK) 13.04.2021 DOA: 12.04.2021 09 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	8,707.20		Nett	10,717.20
Labour	2,740.00	7% GST on	10717.20	750.20
Standard Menu	0.00			
Specialist Job	130.00		Total Payable	11,467.40
Diagnostics Job	0.00			
Sundry/Others	-860.00			
Total(w/o GST)	10,717.20			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO.: AIG

Supplementary For Registration No.: SLP 5231 R

<u>Materials</u>		<u>Cost \$</u>
1	Clip- Hood Stay Rod	2.00 / nec
2	Coolant (4L)	26.00 / nec
3	Retainer Assy- Bumper Cover Mtg (10 pcs)	20.00 / nec
4	Duct Assy- Active Air	78.00 / BR
5	Horn Assy- Low Pitch	79.00 / shorted
6	Horn Assy- High Pitch	79.00 / shorted
		284.00
20% Discount		56.80
		227.20
<u>Labour</u>		
1	Bleed on Engine Coolant System After Repair	120.00 /
2	Replace Front Support Panel	400.00 /
		520.00
Labour & Materials		747.20
7% GST		52.30
Total		799.50

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658

CAR NO: SLP5231R

WIP: 31881

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	FOG LAMP LH CA ✓	? / SUPP	J. K. K. 18/09/21		
2	FOG LAMP RH CA ✓	? / SUPP			
3	BRKT FRT BUMPER LH X	? / SUPP			
4	BRKT FRT BUMPER RH X	? / SUPP			
5	ASSORBED, FRT BUMPER CA ✓	? / SUPP			
6	FRT SUPPORT PNL SA ✓	? / SUPP			
7	DOMNET STND HOLDER MD ✓	? / SUPP			
8	RETAINER, FRT BUMPER SIDE LH ✓	? / SUPP			
9	RETAINER, FRT BUMPER SIDE RH ✓	? / SUPP			
10	SPEAKER ASSY - VEST CA ✓	? / SUPP			
11	RADIATOR INTERIOR ASSY LH ✓	? / SUPP			
12	RADIATOR ASSY LH ✓	? / SUPP			
13	BLOWER ASSY CA ✓	? / SUPP			
14	DOMNET HINGE LH LH ✓	? / SUPP			
15	DOMNET HINGE RH LH ✓	? / SUPP			
16	AIR GUIDER LH CA ✓	? / SUPP			
17	AIR GUIDE RH CA ✓	? / SUPP			
18	BRKT FRT BUMPER REINF LH X	? / SUPP			
19	BRKT FRT BUMPER REINF RH X	? / SUPP			
20	BRKT FRT BUMPER REINF LH LH HL LH	? / SUPP			

OUTSIDE TEMP. SENSOR CA X HL RH

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

DATE

TAKEN BY

MODEL: NIRO

SURVEYOR: STEVE

CAR NO: SLP52312WIP: 31881

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	COBLANT <i>see</i>	? / SUPP	<i>Edine</i>		
2	BUMPER CLIPS (X10) <i>see</i>	? / SUPP			
3	BONNET LOCK <i>8</i>	? / SUPP			
4	LHWP ASSY HEAD <i>PH CAR</i>	? / SUPP			
5	<i>11 11 11</i> LH CAR	? / SUPP	<i>15/02/21</i>		
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP	<i>3-7</i>		
10	<i>Working Day = 2 days</i>	? / SUPP			
11	<i>Support part A = 400 days</i>	? / SUPP			
12		? / SUPP			
13	UPP COVER BUMPER X	? / SUPP	<i>20.04.2021</i>		
14	FR BUMPER LWR 86560-65000	? / SUPP			
15	AIR DUCT BRACKET	? / SUPP			
16	BRACKET BUMPER SIDE RH	? / SUPP			
17	<i>11 11 11</i> LH	? / SUPP	<i>Shaded</i>		
18	RESORRY LHF Fender <i>A 350</i>	? / SUPP			
19	LH RWR RH	? / SUPP			
20	<i>11</i> LH	? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: NIROSURVEYOR: STEVE



HOME

Online



Niro(DE HEV)/2017/G 1.6 GDI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



1/1

System	Status	Result
ENGINE	No Current DTC	Good

System	DTC	Description	State
ENGINE	U100800	Lost Communication With Radiator Shutter (Active Air Flap) (C-CAN)	Pending

S/W Ver.

M-E-K-01-00-0243

VCI Ver.


02.51

ECU Ver.

M-E-K-01-00-0184

OS Ver.

Android 10



Niro(DE HEV)/2017/G 1.6 GDI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



22/22

System	Status	Result
ENGINE	No Current DTC	Good
MCU	No Current DTC	Good
HCULDC	No Current DTC	Good
BMS	No Current DTC	Good
AT	No Current DTC	Good
ESCAHB	No Current DTC	Good

System	DTC	Description	State
IGPM	C181A00	CAN Time-Out AAF	Active

S/W Ver.

M-E-K-01-00-0243

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0184

OS Ver.

Android 10



Niro(DE HEV)/2017/G 1.6 GDI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



22/22

System	Status	Result
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good
PGS	No Current DTC	Good
BSD-L	No Current DTC	Good
BSD-R	No Current DTC	Good

System	DTC	Description	State
IGPM	C181A00	CAN Time-Out AAF	Active

S/W Ver.

M-E-K-01-00-0243

VCI Ver.


02.51

ECU Ver.

M-E-K-01-00-0184

OS Ver.

Android 10



Niro(DE HEV)/2017/G 1.6 GDI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



22/22

System	Status	Result
SMK	No Current DTC	Good
ADM	No Current DTC	Good
CLU	No Current DTC	Good
DDM	No Current DTC	Good
IBU-BC M	No Current DTC	Good
IBU-TP MS	No Current DTC	Good

System	DTC	Description	State
IGPM	C181A00	CAN Time-Out AAF	Active

S/W Ver.

M-E-K-01-00-0243

VCI Ver.


02.51

ECU Ver.

M-E-K-01-00-0184

OS Ver.

Android 10



Niro(DE HEV)/2017/G 1.6 GDI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



22/22

System	Status	Result
IBU-BC M	No Current DTC	Good
IBU-TP MS	No Current DTC	Good
PSM	No Current DTC	Good
WPC	No Current DTC	Good
IGPM	DTC Found.	Fault(01)
VESS	No Current DTC	Good

System	DTC	Description	State
IGPM	C181A00	CAN Time-Out AAF	Active

S/W Ver. M-E-K-01-00-0243

VCI Ver. 02.51

ECU Ver. M-E-K-01-00-0184

OS Ver. Android 10