

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX7083B
LING CHYE SENG
BLK 30 WEST COAST ROAD
03-18
SINGAPORE 127450
TEL : FAX :
PH : 90884099
ATTN :

ESTIMATE BILL

Number : EB00005672
Date : 12/04/2021
Case No : AD00011723
Vehicle No : SGD2250C
Chassis: MR053REH104535960
Year of Mfr 2015
Policy No
Model : TOYOTA COROLLA
ALTIS 1.6 AUTO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	793.20	25	594.90
2	BOOTLID LOCK	1.0	399.50	25	299.63
3	BOOTLID WEATHERSTRIP	1.0	175.80	25	131.85
4	BOOTLID EMBLEM	1.0	50.70	25	38.03
5	BOOTLID LOGO - COROLLA	1.0	41.00	25	30.75
6	BOOTLID LOGO - ALTIS	1.0	45.60	25	34.20
7	BOOTLID LOWER LOCK COVER	1.0	143.10	25	107.33
8	BOOTLID LAMP LH	1.0	203.70	25	152.78
9	BOOTLID LAMP RH	1.0	203.70	25	152.78
10	BOOTLID CHROME	1.0	243.70	25	182.78
11	END PANEL	1.0	670.00	25	502.50
12	END PANEL TOP GARNISH	1.0	241.90	25	181.43
13	TAIL LAMP RH	1.0	391.70	25	293.78
14	TAIL LAMP LH	1.0	391.70	25	293.78
15	TAIL LAMP CLIP LH	4.0	3.50	25	10.50
16	TAIL LAMP CLIP RH	4.0	3.50	25	10.50
17	SPARE TYRE PANEL	1.0	812.10	25	609.08
18	SPARE TYRE PANEL TOP TRIMBOARD	1.0	267.00	25	200.25
19	REAR BUMPER	1.0	556.40	25	417.30
20	REAR BUMPER RETAINER RH	2.0	109.30	25	163.95
21	REAR BUMPER RETAINER LH	2.0	109.30	25	163.95
22	REAR BUMPER BRACKET RH	1.0	60.40	25	45.30
23	REAR BUMPER BRACKET LH	1.0	60.40	25	45.30
24	REAR BUMPER REINFORCEMENT	1.0	399.50	25	299.63
List Price - Parts Sub Total					4,962.28
25	REAR CHASSIS FRAME LH - REPAIR	1.0			
26	REAR CHASSIS FRAME RH - REPAIR	1.0			
27	TAIL LAMP PANEL RH - REPAIR	1.0			
28	TAIL LAMP PANEL LH - REPAIR	1.0			
29	REAR FENDER RH - REPAIR	1.0			
30	REAR FENDER LH - REPAIR	1.0			
31	REAR DOOR RH - REPAIR	1.0			
32	REVERSE SENSOR	1.0	280.00	0	280.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX7083B
LING CHYE SENG
BLK 30 WEST COAST ROAD
03-18
SINGAPORE 127450
TEL : FAX :
PH : 90884099
ATTN :

ESTIMATE BILL

Number : EB00005672
Date : 12/04/2021
Case No : AD00011723
Vehicle No : SGD2250C
Chassis : MR053REH104535960
Year of Mfr : 2015
Policy No :
Model : TOYOTA COROLLA
ALTIS 1.6 AUTO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
33	REVERSE CAMERA	1.0	580.00	0	580.00
34	REAR NUMBER PLATE	1.0	30.00	0	30.00
35	REAR NUMBER PLATE HOLDER	1.0	30.00	0	30.00
Special Nett Price - Parts Sub Total					920.00
Parts Total					5,882.28
36	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,500.00	0	1,500.00
37	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,500.00	0	1,500.00
38	ANTI-RUST COATING	1.0	200.00	0	200.00
39	WIRING	1.0	80.00	0	80.00
40	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					3,430.00
SINGAPORE DOLLARS : NINE THOUSAND NINE HUNDRED SIXTY-FOUR AND CENTS FOURTEEN ONLY			Less Excess	0.00	
			SUBTOTAL	9,312.28	
			GST 7.00%	651.86	
			TOTAL	9,964.14	

Date of accident : 10/04/2021 12:15 PM. Place : 30 NAPPIER ROAD SINGAPORE (258509)

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE