



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65681058



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV05456/SITO WAI SENG Reg No/Reg Date SMR624B / 17/12/201 Date In/Mileage 13/04/2021/ 0 Chassis No GF7W0601733 Engine No 4J11B07748 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	13/04/2021/ 11:34	QUK	282 / Kevin Leong	10022			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT & AFFECTED AREA					450			1350.00
E PNT98000 PAINT WORK ON FRT BUMPER PANEL add Front LH Fender ✓					700			280.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR					2			120.00
M SUNDRY TO TOP UP AIRCON GAS								80.00
M SUNDRY PERFORM RUST PREVENTION								40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME								50.00
M SUNDRY SUNDRIES					20			50.00
HEADLAMP ASSY, LH ✓ CUT					1.00	1948.00	23.00	1499.96
FACE, FR BUMPER ✓ OR					1.00	863.00	23.00	664.51
BRACKET, FR BUMPER SIDE, LH ✓ 1.00 X AIN					1.00	18.00	23.00	13.86
BRACKET, FR BUMPER SIDE, RH ✓ 1.00 X AIN					1.00	18.00	23.00	13.86
EXTENSION, FR BUMPER ✓ OR (Black)					1.00	517.00	23.00	398.09
GARNISH, FR BUMPER, LH ✓ 1.00 X NM					1.00	48.00	23.00	36.96
GARNISH, FR BUMPER SIDE ✓ OR (chrome)					1.00	220.00	23.00	169.40
GARNISH, FR BUMPER SIDE LWR ✓ OR (chrome)					1.00	112.00	23.00	86.24
COVER, FR BUMPER ✓ CUT (Silver)					1.00	361.00	23.00	277.97
REINFORCEMENT, FR BUMPER ✓ BT					1.00	493.00	23.00	379.61
BAR, FR BUMPER GUARD ✓ 1.00 X AIN					1.00	130.00	23.00	100.10
REINF, FR BUMPER SIDE, RH ✓ 1.00 X AIN					1.00	69.00	23.00	53.13
REINFORCEMENT, FR BUMPER ✓ 1.00 X AIN					1.00	135.00	23.00	103.95
REINF, FR BUMPER SIDE, LH ✓ 1.00 X AIN					1.00	60.00	23.00	46.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



LE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV05456/SITO WAI SENG Reg No/Reg Date SMR624B / 17/12/201 Date In/Mileage 13/04/2021/ 0 Chassis No GF7W0601733 Engine No 4J118D7748 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	13/04/2021/ 11:34	QUK	282 / Kevin Leong	10022
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M COVER, HEADLAMP SUPT PANEL	1 X NM	1.00	50.00	23.00	38.50
M GRILLE ASSY, RADIATOR	1 X NM	1.00	550.00	23.00	423.50
M COVER, FR BUMPER INNER	1 X NM	1.00	25.00	23.00	19.25
M BRACKET, RADIATOR GRILLE, RH	1 X NM	1.00	17.00	23.00	13.09
M BRACKET, RADIATOR GRILLE, LH	1 X NM	1.00	13.00	23.00	10.01
M PANEL, HEADLAMP SUPPORT, UPR	1 X NM	1.00	183.00	23.00	140.91
M PANEL, HEADLAMP SUPPORT, LWR	1 X NM	1.00	107.00	23.00	82.39

Estimate

Steve (LKK)

13/4/21, 3.00pm

OD- NM AL

Excess - ?

P/P

My Bel Sel

3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

7% GST on	Nett 6,761.49	473.30
Total Payable		7,234.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.