

VEHICLE NO SKC 7605M BMW

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear Boot Lid		R 1689.00	X
1	Rear Boot Lid BMW Badge		rel 110.20	110.20 29.20
1	Rear Boot Lid 325i Emblem		rel 87.50	87.50
1	Rear Boot Lid inner Lock		^^ 328.00	X
1	Rear Bootlid inner trim	Refix	^^ 0.00	X
2	Rear Bootlid rubber stopper @42.00		^^ 84.00	X
2	Rear Bootlid damper	Refix	^^ 0.00	X
2	Rear Bootlid hinges	Refix	^^ 0.00	X
2	Rear Bootlid reflectors	Refix	^^ 0.00	X
1	Rear Bootlid third brakelight	Refix	^^ 0.00	X
1	Rear Bumper		de 1425.00	1425.00
1	Rear Bumper Towing Cover		^^ 58.00	X
2	Rear Bumper Side Holder @ \$92.00		^^ 184.00	X
1	Rear Reinforcement Outer Frame		ora 140.00	140.00
1	Rear Reinforcement Outer Frame Lower		^^ 120.00	X
1	Rear end panel		DD/Seat 750.00	750.00 715.00
1	End Panel Lock Catch		^^ 60.00	X
1	Boot Weatherstrip		^^ 258.00	X
			5293.70	
			less 5% 264.68	5%
			5029.02	
SPECIAL NETT ITEMS				
1	Rear Licence Plate With Holder		^^ 75.00	X
1set	Reverse sensor		Shudd 380.00	200
1set	Rear Bootlid inner trim clips		^^ 60.00	X
			5544.02	

Not Authorized
 LKKA
 13/4/21
 L/S \$ 3100 |
 4 days
 when after rep-
 * LKKA HSIAO Tony

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

VEHICLE NO **SKC 7605M BMW**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	800.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	600.00	✓
3	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	150.00	80
4	To clear fault code with diagnostic computer and reset to specification	350.00	~x
5	To remove and replace reverse sensors and check for proper function	100.00	50
6	To perform anti-rust treatment on affected areas	90.00	30
	Labour Total :	2090.00	
	TOTAL (PARTS & LABOUR):	7634.02	

NOTE: The parts listed in this PRELIMINARY ESTIMATE will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

9-2456.70
 52

 9-2333.86
 S.N. - 200
 L- 1360

 3893.86
 202

 3115.