



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMP7717G*CPC

Ramasamy Shankar

Blk 529 Hougang Avenue 6
#02-263
Singapore 530529

Vehicle & Document Information

WIP No 49478
Reg No/Reg Date SMP7717G*CPO / 01/11/2019
Date In/Mileage 10
Chassis No WDD2130832A7129690
Engine No 26492080014140
Make/Model MB/E 300 SEDAN
Colour/Trim 029 992 Selenite Gr/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WCV45204	CRDVCH	12/04/2021/ 18:06	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BPNISUN

POLICY NO/ACC DATE : GA568548 // 12/04/2021
DRIVE IN/EXCESS : 12/04/2021 // TP VEH NO SMT2678Y CHINA
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW
BODY PANELS WITH REFINISH

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO
STANDARD SETTINGS. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET

M REAR BUMPER

M REAR BUMPER LOWER

M REAR BUMPER LOWER CHROME MOULDING

M RIGHT REAR EXHAUST CHROME TAILPIPE

M RIGHT REAR EXHAUST TAILPIP BRACKET

M REAR BUMPER COVER F TOWING EYE

1.00	2072.82	00.00	2072.82
1.00	286.94	00.00	286.94
1.00	323.31	00.00	323.31
1.00	421.26	00.00	421.26
1.00	61.82	00.00	61.82
1.00	67.67	00.00	67.67

960 1200.00

600 750.00

0.10 380.00

120.00

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Steve CLKKJ

WKL PL

10/5/21, 10-45am

PIP, P, B, S

LKK Auto Consultants hence notify

Confirmed & accepted by following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Nett	5,683.82
7% GST on	397.87
Total Payable	6,081.69

Validity of this estimate is 14 days from date of issue. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany